

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5441
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 22, 2020

Subject: N202306490 - Safety Recall
N202306491 – Service Update
Service Hood Striker Fracture – Revised Population Continued

Models: 2020 Chevrolet Silverado 2500/3500
2020 GMC Sierra 2500/3500

To: All General Motors Dealers

In continuation of the VIN analysis for Safety Recall N202306490 and accompanying Service Update N202306491, the populations have been reduced a second time. We have identified an additional 105 vehicles to be removed for the Safety Recall, and 33 vehicles to be removed for the Service Update Bulletin.

These VINs were removed from the involved vehicle populations in the Required Field Action section in the Investigate Vehicle History (IVH) screen today. Please hold all warranty transactions until IVH system has been updated.

The attached revised list provides the remaining Vehicle Identification Number (VIN) of all involved vehicles in dealer new inventory for Safety Recall N202306490 and all involved vehicles for Service Update N202306491.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS