

## **Recall 20V-471 Fuel Pump R1200, K1200, K1300, K1600, S1000RR, HP2**

Model Years 2005-2011

BMW Motorrad is announcing a Safety Recall (20V-471) for Model Year 2005-2011 BMW R12000 / K1200/1300/1600, S1000RR, and HP2 models in the US that were subject to Safety Recall 13V-617 and had the **fuel pump repaired with the support ring**. Motorcycles subject to 13V-617 in which the **fuel pump was replaced are not affected**.

Please note that vehicles have not yet been flagged with this recall. We will notify dealers once the campaign flag has been put into place. A Q&A document has been attached for your reference when responding to customer inquiries. If an affected vehicle is at your dealership that is currently experiencing a leak, please create a standard TSARA case. Further information will be published in a Service Information in the next coming weeks.

Aftersales, Motorrad Dealer Direct, Recalls

Aug 24, 2020.