

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: 20V-601 PHEV Module Ordering via IDS
Date: Tuesday, December 22, 2020 12:46:58 PM

Publish Date: December 22, 2020
From: Technical Service
Expiration Date: January 12, 2021

DCSnet Message
Important



Subject: 20V-601 PHEV Module Ordering via IDS

Good Afternoon,

Just a reminder that all vehicles with remedy available for recall 20V-601 must go through the test process outlined in bulletin B61 23 20.

1. The customer can come in for the test, continue to drive the car as prescribed in the bulletin and return for the module replacement when you have all necessary parts.
2. We will be updating the bulletin shortly with Mobile Service language to assist in the test process which can be completed at the customers home and when you have all necessary parts they can come in for the repair.
3. There are currently delays in order processing and delivery from KemKrest, additionally they will be closed on December 24th and 25th and also on December 31st and January 1st. Please allow additional time for the parts to arrive at your location.
4. The module supply is finite to take care of all affected vehicles, we need to ensure that you are only ordering what is necessary after the testing process.

Best regards,

Technical Service and Parts Logistics

Attachments:
No Attachments No Attachments

Recipients: MINI Passenger Cars, CC-MiniManagers
MINI Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel
BMW i, All Offerings, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, CC-All



From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: PHEV Recall Update 20V-601
Date: Tuesday, December 22, 2020 9:26:53 AM

Publish Date: December 22, 2020
From: Technical Service
Expiration Date: January 12, 2021

DCSnet Message
Important



Subject: **PHEV Recall Update – 20V-601**

Good Morning,

We would like to provide you with a short update on the PHEV Recall 20V-601, please note:

1. All Service Loaners and Dealer Demonstrators are now marked as remedy available. Please follow instructions in bulletin B61 23 20 and review the Parts Matrix.
2. Over 200 customer vehicles are marked as remedy available, please check ROSS for more details. Please follow instructions in bulletin B61 23 20 and review the Parts Matrix.
3. All dealer stock vehicles will be returned to BMW NA for repair, please do not request modules for these vehicles.

Please check the defect code in ROSS, WVI or AIR on each vehicle to know how to move forward – see attached for chart.

Additionally, each week the Parts Matrix is updated to provide you with the most up to date information please make sure you review when it is published each Monday.

Best regards and Happy Holidays,

Technical Service

Attachments: [20V-601_PHEV_Chart\[821b23fd\].pdf](#) [20V-601_PHEV_Chart\[821b23fd\].pdf](#)

Recipients: MINI Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel
BMW i, All Offerings, All Regions, All Areas, All Departments, All Personnel
BMW Passenger Cars, CC-All
BMW Passenger Cars, All Offerings, All Regions, All Areas, All Departments, All Personnel

BMW PARTS MATRIX & MAILINGS UPDATE.

Revision Date: December 21, 2020

20V-601 HIGH-VOLTAGE BATTERY.

Order Restriction Level:  Low  Med  High

- Please make sure you are checking the defect code on the VIN and using the correct bulletin.
- Please do not start the repair if the remedy status is a red "X".
- **The modules are shipped from KemKrest, please allow normal processing time for parts to arrive before contacting them for an ETA.**
- Please do not send a TC Case for 20V-601
- Interim customer notification letters have been mailed
- In-Car notifications have been sent

Recall	Defect Code	Bulletin	Model	Repair	Ordering Procedure
20V-601	0061660500	B61 21 20	I12, I15	Module Replacement	<ul style="list-style-type: none"> • If the remedy status is green, submit a Recall IDS Ticket request with the module part number(s) and quantities. All required hardware will be ordered. • If the remedy status is red "X", do not submit: a request, a Recall IDS Ticket, or order any parts listed in the Bulletin
	0061710500	B61 23 20	G05		
	0061700500	M61 07 20	G01, G12, G20, G30 F60		
Recall	Defect Code	Bulletin	Model	Repair	Ordering Procedure
20V-601	0061670500 0061730500	B61 20 20	G01, G05, G12, G20, G30	Repair will be done at BMWNA facility	n/a
	0061650500 0061740500	M61 06 20	F60		
Recall	Defect Code	Bulletin	Model	Repair	Ordering Procedure
Vehicles No Longer Affected by Recall	85800109NA	B61 24 20	G01, G05, G12, G20, G30	Customers have the option to confirm the condition of their high-voltage battery with a 1-time courtesy procedure outlined in the bulletin	n/a