

May 29, 2020

Version 1

Safety Recall: 2018-19 HR-V Fuel Pump Motor**AFFECTED VEHICLES**

Year	Model	Trim Level	VIN Range
2018-19	HR-V	ALL	Check the iN VIN status for eligibility.

BACKGROUND

Due to swelling of the fuel pump motor impeller, the fuel pump may seize and stop working. If this occurs, the engine may not start, or the engine could stall while driving, possibly increasing the risk of a crash.

When this temporary placeholder bulletin appears during an iN VIN status inquiry, this vehicle is subject to a Safety Recall. This vehicle is on **STOP SALE** until further notice. Check for an iN message for further details. Refrain from calling Tech Line for updates.

This bulletin will be updated once Parts Information, Warranty Claim Information, Inspection Procedures, and Repair Procedures are available.

END

CUSTOMER INFORMATION:The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.