

# DON'T IGNORE THIS SAFETY RECALL



**Avoid putting yourself and your loved ones in danger.**  
Evita poner en peligro a tus seres queridos y a ti mismo.

**CALL 1-630-279-2160 TO SCHEDULE YOUR FREE REPAIR**



Toyota Motor Sales, U.S.A., Inc.  
Owner Notification Processing Center  
P.O. Box 149300  
Austin, TX 78714-9300


ELECTRONIC SERVICE REQUESTED

**LAST EIGHT VIN:** [REDACTED]



N608 \*AUTO\*\*ALL FOR AADC 601  
F1R1-000001 1-004

28/548/693



PRESORTED  
STANDARD  
U.S. POSTAGE  
**PAID**  
PALATINE, IL 60095  
PERMIT #675

# WHAT YOU NEED TO KNOW

- **CONDITION** The subject vehicles are equipped with an electronic control unit (ECU) from a specific supplier that is designed to receive signals from crash sensors and deploy the airbags and seatbelt pretensioners. The ECU may not have adequate protection against certain electrical noise that can occur in certain crashes, such as severe underride crashes. This can lead to incomplete or non-deployment of the airbags and/or seatbelt pretensioners. **Airbag and seatbelt pretensioners that do not deploy as intended can increase the risk of injury in a crash.**
- **REMEDY** Any authorized Toyota dealer will install a noise filter between the airbag control module and its wire harness **FREE OF CHARGE** to you.
- **DURATION** The remedy will take approximately between one hour and one hour and 45 minutes. However, depending on the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

**CONDICIÓN** Los vehículos indicados están equipados con una Unidad de Control Electrónico (ECU) de un proveedor específico que está diseñada para recibir señales de los sensores de choque y desplegar las bolsas de aire y los pretensores de los cinturones de seguridad. Es posible que la ECU no tenga la protección adecuada contra ciertos ruidos eléctricos que pueden ocurrir en ciertos choques, como choques graves donde un vehículo se desliza por debajo de la parte trasera o lateral de un camión. Esto puede provocar que las bolsas de aire y/o los pretensores de los cinturones de seguridad no se desplieguen por completo o que no se desplieguen. **Las bolsas de aire y los pretensores de los cinturones de seguridad que no se despliegan como se han diseñado pueden aumentar el riesgo de lesiones en un choque.**

## SCHEDULE YOUR FREE REPAIR TODAY

### YOUR LOCAL DEALER

**Elmhurst Toyota**  
**1-630-279-2160**

▶ **FREE**

Any authorized Toyota dealer will carry out this repair at no cost to you.

▶ **SIMPLE**

Just contact Elmhurst Toyota at **1-630-279-2160**.

▶ **FAST**

The repair on your 2012 Corolla will take approximately between one hour and one hour and 45 minutes depending on your dealer's schedule.

If you are not the current owner of the vehicle, please update your records at [www.toyota.com/recall/update-info-toyota](http://www.toyota.com/recall/update-info-toyota).