

IMPORTANT SAFETY RECALL REMINDER

GSX250R/RZ HEADLAMP BULB



P.O. Box 1100
Brea CA 92822-1100

Vin#

Campaign FF-R15

First Class Mail
U.S. Postage

PAID
Permit No. 1
Torrance, CA



IMPORTANT SAFETY RECALL

CALL NOW TO SCHEDULE YOUR FREE REPAIR.

1 WHY HAVE YOU RECEIVED THIS NOTICE?

In March 2021, owners of select 2018 GSX250R/RZ motorcycles were notified of an important Safety Recall regarding the possible need for replacement of the high/low beam headlamp bulb and retention spring. Parts are available now to complete this important Safety Recall.

2 WHAT SHOULD YOU DO?


Please make an appointment to have your vehicle repaired **free of charge** at any Suzuki Dealer. **To locate your nearest Suzuki Dealer, go to www.suzukicycles.com and click on Find a Dealer at the top of the web page.** Provide the Vehicle Identification Number (VIN) from the front of this card to your Suzuki Dealer.

Affected models of GSX250R/RZ that are operated without the repair may experience premature failure of the high/low beam headlamp bulb, resulting in a sudden loss of illumination which can reduce operator visibility and increase the risk of a crash.

We ask that you immediately make arrangements to have the **FREE** repair performed by your Suzuki Dealer.

Thank you for being a Suzuki Customer.

Suzuki Motor USA, LLC



To find the nearest Suzuki Dealer, scan the QR code above, or go to www.suzukicycles.com and click on **find a dealer** at the top of the web page.

If you are having trouble completing this repair, contact Suzuki Customer Service at **1.714.572.1490** Monday through Friday 7:30am to 4:30pm, PDT