



**SAFETY RECALL NOTICE**

01/08/2021

NO. 2020-01

**TO WHOM IT MAY CONCERN:**

SKEETER Products has been made aware of a potential issue concerning the braking system used on some SKEETER built trailers.

The issue centers around the slider pin(s), which secure the brake caliper assembly in position over the brake rotor. There have been some instances where the slider pin(s) loosened under normal operating conditions.

Effectively immediately, we have issued a safety recall on all SKEETER Built trailers that are affected. Our records indicate that your dealership has been invoiced the following boats with affected trailers:

###SERIAL NUMBERS###

Referencing the Boats that have been retailed sold, SKEETER will be contacting those owners directly and requesting they contact their dealership to set up an immediate appointment to have the slider pins inspected on their trailer. Your dealership must notify the owner of any affected trailer that was actually sold but listed as "unsold" in the report. You must modify all affected trailers in your inventory as well as all customer owned trailers brought to you for this service. Any affected trailer that you purchase from Skeeter in the future may also require modification. If you purchase a trailer from another dealer or Skeeter, check to see if the procedure in this bulletin have already been performed before you sell the trailer.

In the event you discover any trailers with loose and or missing pin(s), please refer to the attached repair process for the appropriate corrective action. The attached repair process encompasses all possible scenarios and provide appropriate process for each. Trailers that are affected should not be operated until they are modified. It is a violation of Skeeter policy for your dealership to deliver any affected trailer(s) to customers until the procedure in this bulletin are performed.

Please file a warranty request online, using job code T300, to receive reimbursement for time expended as outlined in the attached repair process instructions.

Sincerely,

A handwritten signature in black ink, appearing to read "R. Young", is written over a stylized graphic element that resembles a triangle or a boat hull.

Robert Young  
Customer Relations Manager  
SKEETER Products  
903-983-5646  
Robert\_young@yamaha-motor.com