

CAMPAIGN LAUNCH STATUS

N524 RECALL - FRONT SEAT SQUAB COVER MATERIAL



SAFETY RECALL N524 - L551 FRONT SEAT COVER MATERIAL

AFFECTED MODELS

20MY Range Rover Evoque

VOLUME AFFECTED

66 USA 6 CAN

REPAIR

Affected vehicles have been built with front seat Dinamica cloth material that does not conform with FMVSS/CMVSS flammability safety standards. Seat covers will be replaced with conforming product.

REPAIR TIME

Est 0.8hrs+Drive in/out

CAMPAIGN LAUNCH

Target: February 15th, 2021

Notes

Retailer Notification by Aftersales Bulletin is on January 7th, 2021. Three units are unsold.



PRINTED COPIES ARE UNCONTROLLED