



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 11, 2021

Ms. Morgan Fox
Parts and warranty manager
Sutphen Corporation
49 N. Ludlow Rd.
Urbana, OH 43078

NEF-107MR
21V-412

Subject: Wireless Controller Sleep Mode Disabled

Dear Ms. Fox:

This letter serves to acknowledge Sutphen Corporation's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

SUTPHEN/FIRE TRUCK/2019-2020

Mfr's Report Date: June 2, 2021

NHTSA Campaign Number: 21V-412

Components:

EQUIPMENT

Potential Number of Units Affected: 8

Problem Description:

Stuphen Corporation (Stuphen) is recalling certain 2019-2020 Fire Trucks equipped with a battery-powered 3600 wireless remote controller units used to control the movement of electric firefighting monitors in firefighting vehicles. The monitor is used to direct the water stream and adjust the spray pattern. The wireless remote controller's sleep mode is disabled, and results in the batteries discharging faster than normal.

Consequence:

Inability to use the wireless remote controller may hinder the firefighting efforts, increasing the risk of injury.

Remedy:

Dealers will update the wireless remote controller unit software, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Stuphen customer service at 1-614-889-1005.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

As required in Part 573.6(c)(6), in the case of a defect, please provide a chronology of all principal events that were the basis for the determination that the defect related to motor vehicle safety, including a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt.

AMENDED 573 REQUIRED.

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the [affected component]. If your company manufactured the component itself, then please state so in 573.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Sutphen Corporation's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink that reads "Alex Ansley". The signature is fluid and cursive, with a checkmark-like flourish at the end.

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement