



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

June 17, 2021

Michelle Treangen
Genesis Supreme RV
23129 Cajalco Road
Perris, CA 92570

NEF-107KL
21V-415

Subject: Stove Saddle Valves may Leak Gas

Dear Michelle Treangen:

This letter serves to acknowledge Genesis Supreme RV's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

GENESIS SUPREME/VORTEX/2020-2021
GENESIS SUPREME/WANDERER/2020-2021

Mfr's Report Date: June 2, 2021

NHTSA Campaign Number: 21V-415

Components:

EQUIPMENT:APPLIANCE:OVEN/STOVE/COOKTOP
EQUIPMENT:RECREATIONAL VEHICLE/TRAILER:LPG SYSTEMS

Potential Number of Units Affected: 460

Problem Description:

Genesis Supreme RV (Genesis) is recalling certain 2020-2021 Genesis, Vortex, and Wanderer bumper pull and low profile fifth wheel trailers, equipped with Dometic 3-burner cooking stoves. The saddle valve securing bolt may be overtightened, possibly damaging the o-ring seal and causing a continuous gas leak.

Consequence:

A gas leak can increase the risk of a fire.

Remedy:

Genesis Supreme RV will notify owners, and Dometic service centers will install a remedy kit of gaskets, washers, thread locker bolts, and two round orange labels, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Genesis Supreme customer service at 1-951-337-0254.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please ensure the following requirements are met:

The percentage of products estimated to contain the defect or noncompliance (49 CFR 573.6 (c)(4)). If less than 1%, amend your filing to state 1% and provide the actual calculated amount in the first product text box.

AMENDED 573 REQUIRED.

As required in Part 573.6(c)(6), in the case of a defect, please provide a chronology of all principal events that were the basis for the determination that the defect related to motor vehicle safety, including a summary of all warranty claims, field or service reports, and other information (such as the numbers of deaths and/or injuries), with their dates of receipt.

AMENDED 573 REQUIRED.

A description of the manufacturer's program for remedying the defect or noncompliance (49 CFR 573.6 (c)(8)(i)).

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify dealers and/or distributors regarding this safety recall. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If your company does not have dealers or distributors, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Your company must supply the estimated date(s) for which it will notify owners regarding this safety recall. Please be reminded that all owners must be notified of the safety risk associated with this filing within 60 days of the 573 being submitted. If the remedy is not available at that time, mail the interim notice, following it with a second notice once the remedy becomes available. If your company subsequently becomes aware that either the beginning or the completion dates reported to the agency for any of the notifications will be delayed by more than two weeks, your company shall promptly advise the agency of the delay and the reasons therefor, and furnish a revised estimate. If there are no owners involved in this recall, please state so in the 573 (49 CFR 573.6 (c)(8)(ii)).

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Genesis Supreme RV's contact for this recall will be Kristin Lepper who may be reached by email at kristin.lepper@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Alex Ansley", with a long, sweeping flourish extending from the end.

Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement