



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 10, 2021

Mr. Chris Sandvig
Volkswagen Group of America, Inc.
3800 Hamlin Road
Auburn Hills, MI 48326

NEF-107SS
21V-935

Subject: Retaining Ring On Air Suspension Struts May Loosen

Dear Mr. Sandvig:

This letter serves to acknowledge Volkswagen Group of America, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

AUDI/E-TRON GT/2022

Mfr's Report Date: December 1, 2021

NHTSA Campaign Number: 21V-935

Components:

SUSPENSION:FRONT

Potential Number of Units Affected: 10

Problem Description:

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2022 Audi E-Tron GT vehicles. The retaining ring on the air suspension struts may come loose.

Consequence:

A loose retaining ring may allow air to escape, compromising vehicle handling and increasing the risk of a crash.

Remedy:

Dealers will inspect and replace the air suspension struts as necessary, free of charge. Owner notification letters are expected to be mailed January 28, 2022. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 42L2.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:




You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Volkswagen Group of America, Inc.'s contact for this recall will be Sarah Shiver who may be reached by email at sarah.shiver@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement