

Recall Quarterly Report**21E-027**

Manufacturer Name : Tenneco Automotive
NHTSA Recall No. / MFR Recall No. : 21E-027 /
Recall Subject : Upper Ball Joint May Be Installed Incorrectly
Owner Notification Beginning Date : MAY 05, 2021
Owner Notification End Date: MAY 05, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 30, 2021	2021-2	2,394	168	0	9

This Document Last Updated : AUG 02, 2021

Definitions :

- Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).
- Recall Population :** The total number of products recalled by the manufacturer.
- Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.
- Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.
- Total Removed :** Products that have been scrapped, stolen, or exported.