

# Recall Quarterly Report

## 21E-027

**Manufacturer Name :** Tenneco Automotive  
**NHTSA Recall No. / MFR Recall No. :** 21E-027 /  
**Recall Subject :** Upper Ball Joint May Be Installed Incorrectly  
**Owner Notification Beginning Date :** MAY 05, 2021  
**Owner Notification End Date:** MAY 05, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
7	JAN 30, 2023	2022-4	2,394	214	0	9
6	OCT 29, 2022	2022-3	2,394	214	0	9
5	JUL 29, 2022	2022-2	2,394	214	0	9
4	APR 29, 2022	2022-1	2,394	212	0	9
3	JAN 29, 2022	2021-4	2,394	196	0	9
2	NOV 07, 2021	2021-3	2,394	193	0	9
1	JUL 30, 2021	2021-2	2,394	168	0	9

This Document Last Updated : JAN 30, 2023

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.