

Recall Quarterly Report

21E-027

Manufacturer Name : Tenneco Automotive
NHTSA Recall No. / MFR Recall No. : 21E-027 /
Recall Subject : Upper Ball Joint May Be Installed Incorrectly
Owner Notification Beginning Date : MAY 05, 2021
Owner Notification End Date: MAY 05, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	APR 29, 2022	2022-1	2,394	212	0	9
3	JAN 29, 2022	2021-4	2,394	196	0	9
2	NOV 07, 2021	2021-3	2,394	193	0	9
1	JUL 30, 2021	2021-2	2,394	168	0	9

This Document Last Updated : MAY 02, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.