

# Recall Quarterly Report

## 21V-201

**Manufacturer Name :** Porsche Cars North America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 21V-201 /AMA6  
**Recall Subject :** Upper Control Arm Rear Axle Screw Not Tightened  
**Owner Notification Beginning Date :** MAY 21, 2021  
**Owner Notification End Date:** MAY 21, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	APR 21, 2023	2023-1	7	6	0	0
7	JAN 20, 2023	2022-4	7	6	0	0
6	OCT 19, 2022	2022-3	7	6	0	0
5	JUL 25, 2022	2022-2	7	6	0	0
4	APR 18, 2022	2022-1	7	6	0	0
3	JAN 25, 2022	2021-4	7	6	0	0
2	OCT 20, 2021	2021-3	7	5	0	0
1	JUL 15, 2021	2021-2	7	2	0	0

This Document Last Updated : APR 21, 2023

### Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.