

Recall Quarterly Report

21V-201

Manufacturer Name : Porsche Cars North America, Inc.
NHTSA Recall No. / MFR Recall No. : 21V-201 /AMA6
Recall Subject : Upper Control Arm Rear Axle Screw Not Tightened
Owner Notification Beginning Date : MAY 21, 2021
Owner Notification End Date: MAY 21, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	APR 18, 2022	2022-1	7	6	0	0
3	JAN 25, 2022	2021-4	7	6	0	0
2	OCT 20, 2021	2021-3	7	5	0	0
1	JUL 15, 2021	2021-2	7	2	0	0

This Document Last Updated : APR 19, 2022

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.