

**Recall Quarterly Report****21V-404**

**Manufacturer Name :** Mercedes-Benz USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 21V-404 /2021080012  
**Recall Subject :** Side Curtain Air Bags May Not Deploy Properly  
**Owner Notification Beginning Date :** SEP 24, 2021  
**Owner Notification End Date:** SEP 24, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
7	APR 19, 2023	2023-1	16	15	0	0
6	JAN 18, 2023	2022-4	16	15	0	0
5	OCT 13, 2022	2022-3	16	15	0	0
4	JUL 11, 2022	2022-2	16	12	0	0
3	APR 11, 2022	2022-1	16	10	0	0
2	JAN 10, 2022	2021-4	16	7	0	0
1	OCT 13, 2021	2021-3	16	2	0	0

This Document Last Updated : APR 20, 2023

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.