

**Recall Quarterly Report****21V-405**

**Manufacturer Name :** Mercedes-Benz USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 21V-405 /2021060011  
**Recall Subject :** Front Passenger Air Bag May Not Deploy Properly  
**Owner Notification Beginning Date :** JUL 16, 2021  
**Owner Notification End Date:** JUL 16, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	JUL 21, 2023	2023-2	17	16	0	0
7	APR 21, 2023	2023-1	17	16	0	0
6	JAN 20, 2023	2022-4	17	16	0	0
5	OCT 20, 2022	2022-3	17	16	0	0
4	JUL 13, 2022	2022-2	17	15	0	0
3	APR 22, 2022	2022-1	17	13	0	0
2	JAN 11, 2022	2021-4	17	10	0	0
1	OCT 14, 2021	2021-3	17	7	0	0

This Document Last Updated : JUL 24, 2023

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.