

**Recall Quarterly Report****21V-476****Manufacturer Name :** Mack Trucks, Inc.**NHTSA Recall No. / MFR Recall No. :** 21V-476 /SC0426**Recall Subject :** Lower Rear Pivot Cap Screws may be too Short**Owner Notification Beginning Date :** JUL 30, 2021**Owner Notification End Date:** JUL 30, 2021

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	OCT 05, 2022	2023-2	8	8	0	0
7	OCT 05, 2022	2023-1	8	8	0	0
6	OCT 05, 2022	2022-4	8	8	0	0
5	OCT 05, 2022	2022-3	8	8	0	0
4	JUN 30, 2022	2022-2	8	8	0	0
3	APR 07, 2022	2022-1	8	8	0	0
2	JAN 04, 2022	2021-4	8	6	0	0
1	OCT 07, 2021	2021-3	8	4	0	0

This Document Last Updated : OCT 05, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.