

**Recall Quarterly Report****21V-478**

**Manufacturer Name :** Mercedes-Benz USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 21V-478 /2021090008  
**Recall Subject :** Driveshaft May Separate  
**Owner Notification Beginning Date :** OCT 15, 2021  
**Owner Notification End Date:** OCT 15, 2021



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|----------------|-------------------|----------------|-------------------|---------------|
| 2        | APR 11, 2022    | 2022-1         | 1,522             | 361            | 0                 | 0             |
| 1        | JAN 10, 2022    | 2021-4         | 1,522             | 257            | 0                 | 0             |

This Document Last Updated : APR 14, 2022

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.