

Recall Quarterly Report**21V-527**

Manufacturer Name : Mercedes-Benz USA, LLC
NHTSA Recall No. / MFR Recall No. : 21V-527 /2021070032/33
Recall Subject : Side Impact Crash Sensor Connectors May Loosen
Owner Notification Beginning Date : SEP 03, 2021
Owner Notification End Date: SEP 03, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
7	APR 19, 2023	2023-1	542	485	0	0
6	JAN 20, 2023	2022-4	542	472	0	0
5	OCT 20, 2022	2022-3	542	459	0	0
4	JUL 11, 2022	2022-2	542	441	0	0
3	APR 11, 2022	2022-1	542	407	0	0
2	JAN 11, 2022	2021-4	542	327	0	0
1	OCT 14, 2021	2021-3	542	146	0	0

This Document Last Updated : APR 20, 2023

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.