

# Recall Quarterly Report

# 21V-558

**Manufacturer Name :** Suzuki Motor USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 21V-558 /2A97  
**Recall Subject :** Fuel Hose Assembly May Leak Fuel  
**Owner Notification Beginning Date :** AUG 20, 2021  
**Owner Notification End Date:** AUG 20, 2021



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	OCT 05, 2022	2022-3	270	157	6	6
4	JUL 08, 2022	2022-2	270	144	5	3
3	APR 18, 2022	2022-1	270	119	5	1
2	JAN 21, 2022	2021-4	270	97	5	2
1	OCT 15, 2021	2021-3	270	52	5	1

This Document Last Updated : OCT 06, 2022

## Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.