

**Recall Quarterly Report****21V-812****Manufacturer Name :** Volkswagen Group of America, Inc.**NHTSA Recall No. / MFR Recall No. :** 21V-812 /40R7**Recall Subject :** Improperly Tightened Front Wheel Bearing Bolts**Owner Notification Beginning Date :** NOV 02, 2021**Owner Notification End Date:** NOV 02, 2021

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 27, 2023	2023-1	30	27	0	0
5	JAN 26, 2023	2022-4	30	26	0	0
4	OCT 27, 2022	2022-3	30	26	0	0
3	JUL 28, 2022	2022-2	30	24	0	0
2	APR 26, 2022	2022-1	30	24	0	0
1	JAN 27, 2022	2021-4	30	8	0	0

This Document Last Updated : APR 27, 2023

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.