

**Recall Quarterly Report****21V-954**

**Manufacturer Name :** Subaru of America, Inc.  
**NHTSA Recall No. / MFR Recall No. :** 21V-954 /WRL-21  
**Recall Subject :** Tie Rods May Separate  
**Owner Notification Beginning Date :** FEB 07, 2022  
**Owner Notification End Date:** FEB 07, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	JAN 19, 2024	2023-4	1,305	1,220	0	2
7	OCT 23, 2023	2023-3	1,305	1,209	0	2
6	JUL 24, 2023	2023-2	1,305	1,184	0	3
5	APR 28, 2023	2023-1	1,305	1,153	0	3
4	JAN 26, 2023	2022-4	1,305	1,062	0	3
3	OCT 21, 2022	2022-3	1,305	971	0	4
2	JUL 25, 2022	2022-2	1,305	791	0	2
1	APR 27, 2022	2022-1	1,305	480	0	2

This Document Last Updated : JAN 23, 2024

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.