

Part 573 Safety Recall Report

21E-001

Manufacturer Name : Automann Inc.

Submission Date : JAN 07, 2021

NHTSA Recall No. : 21E-001

Manufacturer Recall No. : 0012021



Manufacturer Information :

Manufacturer Name : Automann Inc.

Address : 251 Docks Corner Rd
Monroe Twp NJ 08831

Company phone : 2015294996

Population :

Number of potentially involved : 86,243

Estimated percentage with defect : 1 %

Equipment Information :

Brand / Trade 1 : Automann

Model : Warning Triangle Set

Part No. : 562.9000

Size : NR

Function : NR

Descriptive Information : All 562.9000 Warning Triangle Sets produced by the fabricating supplier for Automann from the start of production until September 21, 2018

Production Dates : NOV 03, 2011 - SEP 21, 2018

Description of Noncompliance :

Description of the Noncompliance : Certain Automann warning triangles may not meet the requirements of FMVSS 125 for color, reflectivity and stability.

FMVSS 1 : 125 - Warning devices

FMVSS 2 : NR

Description of the Safety Risk : Warning triangles that do not meet the requirements of FMVSS 125 may not be sufficiently visible to oncoming traffic and could increase the risk of a crash with a disabled vehicle.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Torch Industrial Co., Ltd

Address : No. 58-6 Donglong Rd.

Longtang Township Taoyuan Hsien Foreign States 32571

Country : Taiwan, Province of China

Chronology :

see attached miscellaneous document

Description of Remedy :

Description of Remedy Program : Automann will provide its distributors with a credit for the full purchase price for all returned or destroyed units in its inventory and will request that distributors contact end-customers who purchased the affected units. End-customers will be instructed to return product to the distributor and will be provided a credit for the full purchase price for all returned units. Distributors will be instructed to return affected units to Automann directly (postage pre-paid), or through their local sales representative.

How Remedy Component Differs from Recalled Component : Automann will provide distributors a credit for the full purchase price for all returned units. Automann ceased importing and distributing the 562.9000 warning triangles from its supplier in September 2018.

Identify How/When Recall Condition was Corrected in Production : Automann ceased importing and distributing the 562.9000 warning triangle kits from its supplier in September 2018, following NHTSA's initial inquiry.

Recall Schedule :

Description of Recall Schedule : Automann will notify its distributors of the recall beginning on January 18, 2021

Planned Dealer Notification Date : JAN 18, 2021 - FEB 01, 2021

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported