

# Part 573 Safety Recall Report

# 21E-021

**Manufacturer Name :** Guangzhou Cougar Trading Co., Ltd.

**Submission Date :** NOV 03, 2021

**NHTSA Recall No. :** 21E-021

**Manufacturer Recall No. :** NR



## Manufacturer Information :

## Population :

**Manufacturer Name :** Guangzhou Cougar Trading Co., Ltd.

**Number of potentially involved :** 23,238

**Address :** Room 609, Shangcheng Exhibition Cent

**Estimated percentage with defect :** 100 %

Guangzhou 00 510000

**Company phone :** 14749343906

## Equipment Information :

**Brand / Trade 1 :** Cougar motor

**Model :** CCD19-6215, CCD19-6322, CCD19-6888, CCD19-6254, CCD19-6398, CCD19-6126, CCD19-6777, CCD19-6881

**Part No. :** Not applicable

**Size :** 9004, 9005, 9006, 9007, 9012

**Function :** light bulb

**Descriptive Information :** Guangzhou Cougar Trading Co., Ltd. as the brand owner is recalling all the above-referenced LED headlamp replacement bulbs marketed and sold in the United States. The recall encompasses 23238 headlamp replacement bulbs marketed and sold in the United States for headlamp purposes. The recall does not apply to bulbs sold outside the United States. Cougar Trading is no dealer network on United States.

**Production Dates :** MAR 15, 2017 - SEP 30, 2020

## Description of Defect :

**Description of the Defect :** The equipment does not meet certain dimensional standards for replaceable light sources set by Standard No. 108, exceeds the luminous flux standards for replaceable light sources established by Standard No. 108, and is devoid of certain markings.

**FMVSS 1 :** 108 - Lamps, reflective devices, and assoc. Equipment

**FMVSS 2 :** NR

**Description of the Safety Risk :** The equipment may, in certain applications, create excessive glare or brightness for oncoming drivers. There are currently no known instances of crash caused by glare or brightness from the bulbs being recalled. However, there is still an increased risk of crash, injury or fire.

**Description of the Cause :** Excessive glare may result because luminous flux output exceed the luminous flux limitations of FMVSS 108

Identification of Any Warning NR  
that can Occur :

## Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

## Supplier Identification :

### Component Manufacturer

Name : Guangzhou Cougar Trading Co., Ltd.

Address : Room 609, Shangcheng Exhibition Center,  
No. 9 Gangtou Street, Yuexiu District, Guangzhou Foreign States 510000

Country : China

## Chronology :

On or about September 25, 2020, NHTSA informed Cougar Motor that, based upon preliminary test results obtained by NHTSA of one model, certain deficiencies were noted which constituted possible noncompliances with FMVSS No. 108.

Testing agency:  
CALCOAST-ITL  
Lighting Technology  
683 Thornton Street  
San Leandro, CA 94577

Test date: 07 August 2020

Prepared for:  
U.S. DEPARTMENT OF TRANSPORTATION  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue SE  
Washington, D.C. 20590

FINAL REPORT 108-CAN-20-003

## Description of Remedy :

**Description of Remedy Program :** The brand owner will send a recall notice to all U.S. based distributors of the above-referenced bulbs and to each U. S.-based customer who purchased these bulbs for whom it has the purchaser's contact information. The brand owner shall also publish a copy of the recall notice on a website it establishes for recall purposes. The brand owner will offer to replace the bulb with halogen headlamp bulbs that comply with FMVSS 108. To qualify for such replacement, a claimant must fill out a recall request form and provide proof of purchase and agree to return the recalled bulb. The brand owner will then have shipped the requisite number of halogen headlamp bulbs to the consumer along with a pre-paid shipping label for return of the LED bulbs.

**How Remedy Component Differs from Recalled Component :** The remedy is designed to ensure that the product not be used as a headlamp bulb.

**Identify How/When Recall Condition was Corrected in Production :** The brand owner has directed the manufacturer not to produce the above-referenced LED bulbs for headlamp usage in the United States.

## Recall Schedule :

**Description of Recall Schedule :** The brand owner will send notices of the recall to the U.S. based distributors by no later than March 26, 2021 and to U.S. based purchasers for whom it has contact information by no later than April 15, 2021. The notification to purchasers will be via U.S. mail or e-mail. The brand owner will also maintain a website for purposes of providing notification about the recall and processing recall requests.

**Planned Dealer Notification Date :** MAR 25, 2021 - MAR 26, 2021

**Planned Owner Notification Date :** APR 01, 2021 - APR 15, 2021

## Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

**Name :** NR

**Address :** NR

NR

**Country :** NR

**Company Phone :** NR

\* NR - Not Reported