

# Part 573 Safety Recall Report

# 21E-050

**Manufacturer Name :** One More Auto Parts Inc.

**Submission Date :** JUN 07, 2021

**NHTSA Recall No. :** 21E-050

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** One More Auto Parts Inc.

**Address :** 101 E Huntington Dr Ste 102  
Arcadia CA 91006

**Company phone :** 7584933

## Population :

**Number of potentially involved :** 4,044

**Estimated percentage with defect :** 100 %

## Equipment Information :

**Brand / Trade 1 :** LASFIT

**Model :** EX-PLAH11FBA

**Part No. :** EX-PLAH11FBA

**Size :** EX-PLAH11FBA

**Function :** EXTERIOR LIGHT

**Descriptive Information :** EXTERIOR LIGHTING: HEADLIGHTS bulb

**Production Dates :** OCT 01, 2019 - OCT 31, 2020

## Description of Defect :

**Description of the Defect :** Onemore auto part INC. is recalling certain aftermarket headlight bulbs, in configurations EX-PLAH11FBA only sold through Amazon.com. Those replaceable light source's maximum luminous flux was above the maximum limit during the first ten minutes, then falls within legal limits; there are dimensional requirements that were not met in that there are no resistive filaments, and does not conform with marking requirements.

**FMVSS 1 :** 108 - Lamps, reflective devices, and assoc. Equipment

**FMVSS 2 :** NR

**Description of the Safety Risk :** The maximum luminous flux was above the maximum limit, and may cause excessive brightness for the first ten minutes of use. At this time, there are no known instances of crashes or injuries caused by excessive brightness by use of this bulb

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

**Involved Components :**

Component Name : NR

Component Description : NR

Component Part Number : NR

**Supplier Identification :****Component Manufacturer**

Name : Guangzhou jiujiayi dianzikeji youxiangon

Address : guangzhoushi baiyunqu renhezhen gonghuag  
GuangZhou Foreign States 510470

Country : China

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : One more auto parts inc. will notify customers to change back to halogen, instructing them to return the bulbs for a full refund, To qualify for such replacement, a claimant must fill out a recall request form and provide proof of purchase, and agree to return the recalled bulb. The recall is expected to begin July 20, 2021, customer can contact onemore customer service email recall2021@onemoreauto.com

How Remedy Component Differs from Recalled Component : EX-PLAH11FBA

Identify How/When Recall Condition was Corrected in Production : Unknown. one more auto parts inc. is not the manufacturer. The manufacturer was contacted and made aware of the issue. One more auto parts inc. didn't sell these headlamps already on Oct, 31th,2020.

**Recall Schedule :**

Description of Recall Schedule : Onemore auto parts does not have dealers or distributors. One more auto parts inc. didn't sell these headlamps already on Oct, 31th,2020.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

**Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

\* NR - Not Reported