

Part 573 Safety Recall Report

21E-050

Manufacturer Name : One More Auto Parts Inc.

Submission Date : AUG 18, 2021

NHTSA Recall No. : 21E-050

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : One More Auto Parts Inc.

Address : 101 E Huntington Dr Ste 102

Arcadia CA 91006

Company phone : 7584933

Population :

Number of potentially involved : 4,044

Estimated percentage with defect : 100 %

Equipment Information :

Brand / Trade 1 : LASFIT

Model : EX-PLAH11FBA

Part No. : EX-PLAH11FBA

Size : EX-PLAH11FBA

Function : EXTERIOR LIGHT

Descriptive Information : EXTERIOR LIGHTING: HEADLIGHTS bulb

Production Dates : OCT 01, 2019 - OCT 31, 2020

Description of Defect :

Description of the Defect : Onemore auto part INC. is recalling certain aftermarket headlight bulbs, in configurations EX-PLAH11FBA only sold through Amazon.com. Those replaceable light source's maximum luminous flux was above the maximum limit during the first ten minutes, then falls within legal limits; there are dimensional requirements that were not met in that there are no resistive filaments, and does not conform with marking requirements.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : The maximum luminous flux was above the maximum limit, and may cause excessive brightness for the first ten minutes of use. At this time, there are no known instances of crashes or injuries caused by excessive brightness by use of this bulb

Description of the Cause : Excessive glare may result because luminous flux output exceed the luminous flux limitations of FMVSS 108. The equipment may, in certain applications, create excessive glare or brightness for oncoming drivers. There are currently no known instances of crash caused by glare or brightness from the bulbs being recalled.

Identification of Any Warning that can Occur : These bulbs will not be used as headlight bulbs.

Involved Components :

Component Name : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Guangzhou jiujiayi dianzikeji youxiangon

Address : guangzhoushi baiyunqu renhezhen gonghuag
GuangZhou Foreign States 510470

Country : China

Chronology :

The equipment does not meet certain dimensional standards for replaceable light sources set by Standard No. 108, exceeds the luminous flux standards for replaceable light sources established by Standard No. 108, and is devoid of certain markings.

Description of Remedy :

Description of Remedy Program : One more auto parts inc. will notify customers to change back to halogen, instructing them to return the bulbs for a full refund, To qualify for such replacement, a claimant must fill out a recall request form and provide proof of purchase, and agree to return the recalled bulb. The recall is expected to begin July 20, 2021, customer can contact onemore customer service email recall2021@onemoreauto.com

How Remedy Component Differs from Recalled Component : EX-PLAH11FBA

Identify How/When Recall Condition was Corrected in Production : Once more Auto parts sent notification emails to all the customers from 21th, July 2021. And we didn't sell this item from 31th, Oct 2020.

Recall Schedule :

Description of Recall Schedule : of the recall to the customers who purchased the items from our online store since this is the only channel we have. The notification to purchasers was sent via e-mail from 21th, July 2021.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : NR

Address : NR

NR

Country : NR

Company Phone : NR

* NR - Not Reported