

Part 573 Safety Recall Report

21V-116

Manufacturer Name : Black Series Campers Inc.

Submission Date : MAR 10, 2021

NHTSA Recall No. : 21V-116

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Black Series Campers Inc.

Address : 19501 E Walnut dr s

City of Industry CA 91748

Company phone : 833-822-6737

Population :

Number of potentially involved : 412

Estimated percentage with defect : 80 %

Vehicle Information :

Vehicle 1 : 2020-2021 Black Series Camper C12, C13, C15, HQ12, HQ15, HQ17, HQ19, HQ19T, HQ21, HQ22T

Vehicle Type : TRAILERS

Body Style : ALL

Power Train : NR

Descriptive Information : Certain models have Curt part 52041 and 52044 breakaway kits with batteries that can become depleted, which can lead to an overload on the main battery

Production Dates : OCT 01, 2020 - FEB 10, 2021

VIN Range 1 : Begin : 4B9B1AB10KA165230 **End :** 4B9B1AD2XMA165616 Not sequential

Description of Defect :

Description of the Defect : When the emergency breakaway system pin is pulled and not replaced the electrical circuit is closed. When the small breakaway battery (CURT) is depleted, the emergency brake system draws through the charger from the main battery. The total assumed draw is around 10amps - 12 amps. The charger is rated around 5amps. This causes an overload which could lead to a fire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Increased risk of fire and/or property damage.

Description of the Cause : When the emergency breakaway pin/clip is pulled and is not replaced, the small battery (CURT) continuously drains until it is depleted.

Identification of Any Warning that can Occur : Smoke or fire from the battery compartment.

Involved Components :

Component Name 1 : Curt Breakaway Kit

Component Description : NR

Component Part Number : 52041 & 52044

Supplier Identification :

Component Manufacturer

Name : CURT Manufacturing, LLC

Address : 6208 Industrial Drive
Eau Claire Wisconsin 54701

Country : United States

Chronology :

We first received a unit with burn damage on January 27, 2021 from a dealership. Upon visual inspection, it was determined that the burn was isolated to the components location. We have been conducting testing during the month of February to identify the issue. New components are being tested. During the third week of February the issue was sent to the board to determine the next steps. The board determined there was a safety defect and the recall was filed February 26, 2021.

Description of Remedy :

Description of Remedy Program : Black Series Campers will supply the updated components. BSC will pay/reimburse for the labor of the replacement and BSC will reimburse the value of the part and the labor if the component has been replaced.

How Remedy Component Differs from Recalled Component : The new component works and upon rigorous testing, no identifiable issues were found.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Black Series will notify owner and dealers within 60 days of filing this report.

Planned Dealer Notification Date : APR 10, 2021 - APR 16, 2021

Planned Owner Notification Date : APR 10, 2021 - APR 15, 2021

* NR - Not Reported