

# Part 573 Safety Recall Report

## 21V-397

**Manufacturer Name :** KZRV, L.P.

**Submission Date :** JUN 07, 2021

**NHTSA Recall No. :** 21V-397

**Manufacturer Recall No. :** KZ-2021-02



### Manufacturer Information :

Manufacturer Name : KZRV, L.P.

Address : 0985 N 900W

Shipshewana IN 46565

Company phone : 800-768-4016x154/153

### Population :

Number of potentially involved : 117

Estimated percentage with defect : 95 %

### Vehicle Information :

Vehicle 1 : 2021-2021 KZ RV SportTrek

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Circuits run with a 14/2 wire are incorrectly protected by a 20 amp circuit breaker.

Production Dates : FEB 11, 2021 - MAY 20, 2021

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Vehicle 2 : 2021-2021 KZ RV Stratus

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Circuits run with a 14/2 wire are incorrectly protected by a 20 amp circuit breaker.

Production Dates : FEB 11, 2021 - MAY 20, 2021

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

### Description of Defect :

Description of the Defect : The water heater circuits are run with 14/2 wire and connected to a 20 amp circuit breaker instead of a 15 amp circuit breaker.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If an issue develops, the wiring could overheat and melt before the circuit breaker trips which could result in a fire.

Description of the Cause : Production error.

Identification of Any Warning None  
that can Occur :

### Involved Components :

Component Name 1 : Circuit Breaker

Component Description : 20 amp circuit breaker

Component Part Number : 123407

### Supplier Identification :

#### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

### Chronology :

5/19/21 - PDI department inspects a unit built in Plant #8. They note the improper protection of the 14/2 wire on the water heater circuit. Yard inventory from this plant is placed on hold.

5/20/21 - The inventory in the yard is inspected and found with the same defect. These units are corrected. Investigation is conducted and found a wire supply change occurred in January 2021.

5/21/21 - A safety committee meeting is held and determines a recall should be issued.

### Description of Remedy :

Description of Remedy Program : Replace the 20 amp circuit breaker with a 15 amp circuit breaker.

How Remedy Component Differs NR  
from Recalled Component :

Identify How/When Recall Condition All wire circuits are paired with proper circuit breakers.  
was Corrected in Production :

### Recall Schedule :

Description of Recall Schedule : KZ will notify the dealers and owners of these recreational vehicles by letter. A final copy of the owner letter and dealer repair instructions will be provided to NHTSA.

Planned Dealer Notification Date : JUL 23, 2021 - JUL 23, 2021

Planned Owner Notification Date : JUL 23, 2021 - JUL 23, 2021

\* NR - Not Reported