

Part 573 Safety Recall Report

21V-436

Manufacturer Name : Four Guys Stainless Tank & Equip., Inc.

Submission Date : NOV 03, 2021

NHTSA Recall No. : 21V-436

Manufacturer Recall No. : NR



Manufacturer Information :

Population :

Manufacturer Name : Four Guys Stainless Tank & Equip., Inc.

Number of potentially involved : 1

Address : 230 Industrial Park Road

Estimated percentage with defect : 1 %

P.O. BOX 90 Meyersdale PA 15552

Company phone : 814-634-8373

Vehicle Information :

Vehicle 1 : 2020-2020 Spartan Gladiator

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Received a letter from the manufacture

Production Dates : OCT 04, 2019 - APR 15, 2020

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : It is possible that reduced battery life in the controller could increase the likelihood that the batteries will become depleted while the controller is in use.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The firefighter would need to revert to using a hard-wired controller on the vehicle, or use the manual hand controls located directly on the affected monitor. This could slow the progress of firefighting efforts and may increase the risk of injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : 3600 Wireless remote controller

Component Description : Wireless Deck Gun controller

Component Part Number : 36000015

Supplier Identification :

Component Manufacturer

Name : Akron Brass

Address : 343 Venture Blvd.

Wooster Ohio 44691

Country : United States

Chronology :

Received a letter from the supplier Akron Brass of the defected product dated May 27, 2020 stating the sleep mode after 30 seconds of inactivity by the user does not initiate. Four Guys Stainless Tank & Equip, Inc. was the purchaser. Affected Controllers need to be returned to Akron Brass for a software update. Akron Brass will update or replace the affected units free of charge.

Description of Remedy :

Description of Remedy Program : Affected Controllers need to be returned to Akron Brass for a software update. Akron Brass will update or replace the affected units free of charge.

How Remedy Component Differs from Recalled Component : updated software

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported