

Part 573 Safety Recall Report

21V-444

Manufacturer Name : Forest River, Inc.**Submission Date :** JUN 11, 2021**NHTSA Recall No. :** 21V-444**Manufacturer Recall No. :** 501-1366**Manufacturer Information :****Population :**

Manufacturer Name : Forest River, Inc.

Number of potentially involved : 10

Address : 55470 CR 1

Estimated percentage with defect : 100 %

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Vehicle Information :

Vehicle 1 : 2021-2021 Forest River Inc. East to West Alta Travel Trailer

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Since the inception of the ALT1900MMK model, the LP/CO Detector has been in a location that is outside of the manufacturers required height measurement.
2021 Alta Travel Trailer - ALT1900MMK - 10

Production Dates : JUN 03, 2021 -JUN 04, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The LP/CO detector was installed outside of the manufacturers required height measurement.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A consumer may not be alerted to a LP Gas Leak or Carbon Monoxide incident, potentially increasing the risk of injury.

Description of the Cause : Engineering and Production Error.

Identification of Any Warning : None
that can Occur :

Involved Components :

Component Name 1 : LP/CO detector

Component Description : LP/CO detector

Component Part Number : RVCOLP-2B

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

On June 10, 2021, during a routine Corporate Quality Audit at the manufacturing plant, it was discovered that the LP/CO Detector was install at 24". The manufacturer's instructions require it to be installed between 4" – 20".

The new detector will now be installed in the correct location. This is not a component failure, this is an installation issue.

On June 11, 2021, Forest Rivers Corporate Recall Committee voted to recall.

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to the Consumer and Dealer. An authorized Forest River Dealer or Service Center will need to perform the repair. A New Detector will be installed at the correct height.

What is the Forest River Customer Service Phone Number? (574)
264-6664

How Remedy Component Differs from Recalled Component : The new detector will now be installed in the correct location. This is not a component failure, this is an installation issue.
Component Name LP/CO detector
Component Description LP/CO detector

Part Number RVCOLP-2B

Identify How/When Recall Condition was Corrected in Production : The issue was corrected in production and in the manufacturing plant-holding yard the week of June 11, 2021.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : JUL 20, 2021 - JUL 20, 2021

Planned Owner Notification Date : JUL 20, 2021 - JUL 20, 2021

* NR - Not Reported