

# Part 573 Safety Recall Report

## 21V-604

**Manufacturer Name :** Newmar Corporation

**Submission Date :** OCT 13, 2021

**NHTSA Recall No. :** 21V-604

**Manufacturer Recall No. :** Cummins 21E-063



### Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street  
PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

### Population :

Number of potentially involved : 169

Estimated percentage with defect : 100 %

### Vehicle Information :

Vehicle 1 : 2021-2022 Newmar Dutch Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Spartan chassis, A fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire. Dutch Star= 99 units

Production Dates : OCT 23, 2020 - JUL 23, 2021

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Vehicle 2 : 2021-2022 Newmar New Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Spartan chassis, A fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire. New Aire=30 units

Production Dates : OCT 23, 2020 - JUL 23, 2021

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Vehicle 3 : 2021-2022 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes built on a Spartan chassis, A fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire.  
Ventana= 40 units

Production Dates : OCT 23, 2020 - JUL 23, 2021

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential

### Description of Defect :

Description of the Defect : On certain motorhomes built on a Spartan chassis, A fuel leak may occur in the fuel hoses between the fuel pump and the remote fuel filter head. A fuel leak in the presence of an ignition source may increase the risk of fire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A fuel leak in the presence of an ignition source may increase the risk of fire.

Description of the Cause : NR

Identification of Any Warning NR  
that can Occur :

### Involved Components :

Component Name 1 : stage 2 fuel hose assembly

Component Description : Pressurized fuel hoses

Component Part Number : Numbers FF90942, FF90943, FF90944, FF91044) which includes pressurized fuel hoses.

### Supplier Identification :

#### Component Manufacturer

Name : Cummins, Inc.

Address : P.O. Box 3005

Columbus Indiana 47202  
Country : United States

## Chronology :

On 07/28/2021, The Shyft Group #21V-556 sent Newmar notice of defect on Spartan chassis. Cummins #21E-063. On August 4, 2021 Newmar made a decision there is a potential safety defect on Newmar motorhomes and gave notice to NHTSA. If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

## Description of Remedy :

Description of Remedy Program : Cummins is currently developing a schedule for beginning the repairs. Cummins expects to send either an interim owner notification or owner notification by no later than September 3, 2021. If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department  
Newmar Corporation  
355 N Delaware St  
Nappanee, IN 46550-0030

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : On or before 10/03/2021, customer/dealer letters will be sent out.

Planned Dealer Notification Date : OCT 03, 2021 - OCT 03, 2021

Planned Owner Notification Date : OCT 03, 2021 - OCT 03, 2021

\* NR - Not Reported