

Part 573 Safety Recall Report

21V-692

Manufacturer Name : Forest River, Inc.**Submission Date :** SEP 03, 2021**NHTSA Recall No. :** 21V-692**Manufacturer Recall No. :** 225-1416**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.

Address : 55470 CR 1

P.O. Box 3030 Elkhart IN 46515-3030

Company phone : 1-800-348-7440

Population :

Number of potentially involved : 175

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2022 Coachmen Nova Class B Motorhomes

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Using production records of all NAB20RB and NAB20RBM units manufactured by the plant since inception to current date that did not get an optional Lithium Battery Option the scope of vehicles were able to be determined.

2021	Nova	NAB20RB	163
2021	Nova	NAB20RBM	2
2022	Nova	NAB20RB	9
2022	Nova	NAB20RBM	1
Grand Total			175

Production Dates : FEB 20, 2020 - AUG 31, 2021

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

Description of the Defect : The AGM Battery was installed on the interior of the vehicle, not inside a battery box vented to the exterior. During charging or overcharging the battery may release hydrogen gas into the vehicle interior.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This condition may result in personal injury or death.

Description of the Cause : The AGM Battery was installed on the interior of the vehicle, not inside a battery box vented to the exterior.

Identification of Any Warning that can Occur : The Carbon Monoxide alarm may sound.

Involved Components :

Component Name 1 : 8D AGM Battery

Component Description : 8D AGM Battery

Component Part Number : N/A

Component Name 2 : Battery Box

Component Description : Battery Box

Component Part Number : N/A

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On 8/19/2021, the manufacturing plant received information from a Dealer that the customers' complaint is that they smell sulfur from battery inside compartment.

On 8/24/2021 thru 8/31/2021, the manufacturing plant received 4 additional complaints.

On 8/31/2021, Forest Rivers Office of Corporate Compliance was notified of this issue. All vehicles in Forest Rivers' possession that were affected were locked down until a battery box can be installed and vented to the exterior of the vehicle.

On 9/3/2021 – Forest Rivers' Office of Corporate Compliance voted to recall.

Description of Remedy :

Description of Remedy Program : Forest River will provide all parts and labor free of charge to the dealer and the customer. A battery box will be installed and vented to the exterior of the vehicle.

What is the Forest River Customer Service Phone Number? 574-825-6319 or (574) 825-6625

How Remedy Component Differs from Recalled Component : N/A or "8D AGM Battery"
A new battery box will be installed that will be vented to the outside of the vehicle.

Identify How/When Recall Condition was Corrected in Production : During the week of August 31, 2021, all vehicles affected were locked down until a battery box can be installed and vented to the exterior of the vehicle.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River will send suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles (as needed) once a formal NHTSA I.D. is provided. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : OCT 13, 2021 - OCT 13, 2021

Planned Owner Notification Date : OCT 13, 2021 - OCT 13, 2021

* NR - Not Reported