

Part 573 Safety Recall Report

21V-993

Manufacturer Name : Cruiser RV

Submission Date : DEC 20, 2021

NHTSA Recall No. : 21V-993

Manufacturer Recall No. : TBD



Manufacturer Information :

Manufacturer Name : Cruiser RV

Address : 7805 North State Road 9
PO Box 130 Howe IN 46746

Company phone : 866-277-5630

Population :

Number of potentially involved : 110

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2021-2022 Cruiser Shadow Cruiser

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The Federal certification tire placard does not have the correct tire size listed.

Production Dates : APR 27, 2021 - OCT 14, 2021

VIN Range 1 : Begin : 5RXDB3021M1473157 End : 5RXDB3025N1491114 ☒ Not sequential

Vehicle 2 : 2022-2022 Cruiser Twilight

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : The Federal certification tire placard does not have the correct tire size listed.

Production Dates : AUG 20, 2021 - OCT 07, 2021

VIN Range 1 : Begin : 5RXPB3029N1484180 End : 5RXPB3022N1490371 ☒ Not sequential

Description of Noncompliance :

Description of the Noncompliance : Travel Trailers do not conform to 49 CFR Part 567 – Certification and Federal Motor Vehicle Safety Standard 120, Tire Selection and Rims for Motor Vehicles Other Than Passenger Cars.

FMVSS 1 : 120 - Wheels and rims- other than passenger cars

FMVSS 2 : NR

Description of the Safety Risk : The owner would not know the correct tire for replacement if the need would

Description of the Safety Risk : arise. This could lead to the incorrect tire and or rim being substituted. This could lead to an increased chance of towing issues and a crash or personal injury.

Description of the Cause : The tire placard and fed tags were printed with ST225/75R15E tires and actually had ST205/75R14D tires installed

Identification of Any Warning that can Occur : N/A

Involved Components :

Component Name 1 : Tire Placard

Component Description : Tire and Rim information placard

Component Part Number : na

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

11/29 - Engineering noted a discrepancy of tire sizes during an audit of our fed tags. 12/1 - ran reports and researched scope. 12/10 - found 3 brands and models that listed the incorrect tire sizes. 12/15 - sent to the safety committee.

Description of Remedy :

Description of Remedy Program : The manufacture will send out replacement certification labels. This will be corrected at no expense to the owner. All reimbursements will be covered by Heartland's general reimbursement plan.

How Remedy Component Differs from Recalled Component : The tire size listed will be corrected on the new tire placard. The correct tire size is ST205/75R14D.

Identify How/When Recall Condition was Corrected in Production : We corrected the tire sizing in the system so the VIN tags and tire placard will print properly. This was corrected as soon as the audit discovered the discrepancy.

Recall Schedule :

Description of Recall Schedule : The mailings will begin once approval is received

Planned Dealer Notification Date : FEB 13, 2022 - FEB 13, 2022

Planned Owner Notification Date : FEB 13, 2022 - FEB 13, 2022

* NR - Not Reported