

**Recall Annual Report****21V-527**

**Manufacturer Name :** Mercedes-Benz USA, LLC  
**NHTSA Recall No. / MFR Recall No. :** 21V-527 /2021070032/33  
**Recall Subject :** Side Impact Crash Sensor Connectors May Loosen  
**Owner Notification Beginning Date :** SEP 03, 2021  
**Owner Notification End Date:** SEP 03, 2021

**Annual Reports**

Report #	Submission Date	Reporting Period	Recall Population	Total Remedied	Total Unreachable	Total Removed
1	JUL 17, 2024	2023-3 to 2024-2	542	503	0	0

**Quarterly Reports**

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	JUL 20, 2023	2023-2	542	490	0	0
7	APR 19, 2023	2023-1	542	485	0	0
6	JAN 20, 2023	2022-4	542	472	0	0
5	OCT 20, 2022	2022-3	542	459	0	0
4	JUL 11, 2022	2022-2	542	441	0	0
3	APR 11, 2022	2022-1	542	407	0	0
2	JAN 11, 2022	2021-4	542	327	0	0
1	OCT 14, 2021	2021-3	542	146	0	0

This Document Last Updated : JUL 18, 2024

**Definitions :**

**Reporting Period:** The reporting period is the manufacturer is reporting recall completion figures.

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.