

# Recall Annual Report

# 21V675



U.S. Department  
of Transportation  
  
National Highway  
Traffic Safety  
Administration

**Manufacturer Name:** Subaru of America, Inc.  
**NHTSA Recall No. / MFR Recall No.:** 21V675 / WRI-21  
**Recall Subject:** Lower Control Arm Weld Failure  
**Owner Notification Beginning Date:** Sep 03, 2021

## Annual Reports

Report #	Submission Date	Update Date	Reporting Period	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	Jul 22, 2025	Jul 22, 2025	2024-3 to 2025-2	802	787	5	0
1	Jul 24, 2024	Jul 31, 2024	2023-3 to 2024-2	802	779	8	0

## Quarterly Reports

Report #	Submission Date	Update Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
8	Jul 24, 2023	Jul 31, 2023	2023-2	802	777	24	0
7	Apr 28, 2023	May 01, 2023	2023-1	802	771	10	0
6	Jan 26, 2023	Jan 27, 2023	2022-4	802	771	10	0
5	Oct 21, 2022	Oct 26, 2022	2022-3	802	767	11	0
4	Jul 25, 2022	Jul 28, 2022	2022-2	802	764	13	0
3	Apr 27, 2022	May 02, 2022	2022-1	802	762	15	0
2	Jan 27, 2022	Jan 27, 2022	2021-4	802	619	0	4
1	Oct 29, 2021	Nov 05, 2021	2021-3	802	554	0	0

This document last updated: Jul 23, 2025

### Definitions:

**Reporting Period:** The reporting period the manufacturer is reporting recall completion figures.

**Report Quarter:** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

**Recall Population:** The total number of products recalled by the manufacturer.

**Total Remedied:** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable:** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed:** Products that have been scrapped, stolen, or exported.

