



New Safety Recall Advanced Communication – Y85

FCA US LLC (FCA US) has announced an equipment safety recall on certain Trailer Reverse Steering Control Modules (TRSCMs).

- Mopar Trailer Reverse Steering Control Module 68423566AE
- Mopar Trailer Reverse Steering Control Module 68423566AF

REASON FOR THIS SAFETY RECALL

Some of the above TRSCMs may prevent the rearview image from displaying under certain conditions. An Electronic Throttle Control warning indicator may also be illuminated in the instrument panel cluster. If installed in a vehicle, the vehicle operator will notice that the rearview image is not displayed if attempting to reference the image while backing. If this warning is not heeded, backing without verifying it is safe to do so could lead to an increased risk of injury to people outside the vehicle.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 571.111 S6.2.6 which requires that "The rear visibility system default to the rearview image being visible, and meet the requirements of FMVSS 571.111 S6.2.1 (field of view) and S6.2.2 (image size) at the beginning of each backing event, regardless of any modifications to the field of view that the driver had previously selected."

SERVICE ACTION

FCA US will conduct a voluntary safety recall on all affected parts to repurchase suspect TRSCMs. The remedy for this condition is not currently available. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 4th Quarter of 2022.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC