



New Safety Recall Advanced Communication – Y04

FCA US LLC (FCA US) has announced a safety recall on certain 2021 Model Year (DS) Ram 1500 Pickup vehicles equipped with non-adjustable pedals (sales code XA8).

REASON FOR THIS SAFETY RECALL

Some of the above vehicles may have been built without the clip which retains the master cylinder push rod to the brake pedal. A vehicle built without the clip could allow the master cylinder push rod to disconnect from the brake pedal pin, separating the brake pedal from the brake system. A disconnected master cylinder push rod results in the driver being unable to apply the service brakes using the brake pedal, which can cause a vehicle crash without prior warning. The parking brake function is unaffected.

FCA US recommends that owners DO NOT DRIVE their vehicles until they receive instructions on how to have their vehicle inspected, and repaired if necessary.

SERVICE ACTION

FCA US will conduct a voluntary safety recall to inspect for the brake clip and install a clip if missing. Involved Dealers and vehicle Owners are currently being notified of this safety recall by way of established communication methods. This recall is estimated to launch by February 15, 2021.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations
FCA US LLC