

**View Message**

<b>Sent on</b>	04	09	2021	<b>Expires on</b>	05	09	2021
<b>From</b>	American Honda Powersports Products						
<b>Subject</b>	SAFETY RECALL: CBR1000RR-R #1 - Rear Cushion Connecting Plates now available						

April 09, 2021

Re: **SERVICE BULLETIN NOW AVAILABLE - 2021 CBR1000RR-R (SP) – REAR CUSHION CONNECTING PLATES**

Dear Honda Powersports Dealer:

On Monday, April 05, 2021, Honda issued a **STOP SALE NOTICE** on **CERTAIN** 2021 CBR1000RR-R (SP) motorcycles to inspect the rear cushion connecting plates and, if necessary, perform a repair.

**SERVICE BULLETIN**

Service Bulletin **CBR1000RR-R #1** contains all information to perform the repair and is now available on **iN** by clicking [here](#).

**Make sure all departments in your dealership are aware of this action.**

If you have any questions, please contact TechLine through *TechLine Connect* on **iN**.

Sincerely,

**American Honda Motor Co., Inc.**  
Powersports Products