



BENTLEY

Bentley
Bulletin

Aftersales

21-030

May 7, 2021

To: Sales, Marketing, Parts, and Service

Subject: Stop Sale/Stop Delivery: Bentley: Rear Training Arm Nut Recall 21V-276

In the Americas, Bentley Motors is voluntarily recalling 206 Bentley Bentley V8 vehicles built between October 2020 and December 2020. Due to stress corrosion cracking on lock nuts of particular production batches, the lock nut of the eccentric bolt on the lower lever arm of the rear axle may break which may cause alterations in the wheel alignment of the rear axle.

The repair for this recall is not yet available. Bentley will advise when the repair is available.

Every affected inventory vehicle must be REMEDIED BEFORE DELIVERY TO CONSUMERS. Therefore, please carry out following Stop Sale/Stop Delivery immediately.

IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED.

DEALERS SHOULD NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Ensure all relevant dealership personnel are aware of this notice so they are able to address customer questions. Contact your ASM if you require additional assistance. Please direct press inquiries to Erin Bronner at erin.bronner@bentley-usa.com.

Should vehicles have already been delivered to customers in the meantime contrary to expectations, please report them to stephen.worrall@bentley-usa.com

Stop Sales list of affected VINs:

SJAAM2ZV7MC033845	SJAAM2ZV0MC034030	SJAAM2ZV3MC034054
SJAAM2ZV6MC034050		

The list of affected VIN which have been reported retailed and cannot be resold:

SJAAM2ZV0MC033766	SJAAM2ZV3MC034040	SJAAM2ZV7MC034008
SJAAM2ZV0MC033797	SJAAM2ZV3MC034166	SJAAM2ZV7MC034056



BENTLEY

Bentley
Bulletin

Aftersales

21-030

May 7, 2021

To: Sales, Marketing, Parts, and Service

Subject: Stop Sale/Stop Delivery: Bentayga: Rear Training Arm Nut Recall

SJAAM2ZV0MC033833	SJAAM2ZV3MC034216	SJAAM2ZV7MC034171
SJAAM2ZV0MC033847	SJAAM2ZV3MC034295	SJAAM2ZV7MC034199
SJAAM2ZV0MC033850	SJAAM2ZV4MC033771	SJAAM2ZV8MC033773
SJAAM2ZV0MC033878	SJAAM2ZV4MC033799	SJAAM2ZV8MC033790
SJAAM2ZV0MC033881	SJAAM2ZV4MC033818	SJAAM2ZV8MC033806
SJAAM2ZV0MC033895	SJAAM2ZV4MC033821	SJAAM2ZV8MC033837
SJAAM2ZV0MC033900	SJAAM2ZV4MC033835	SJAAM2ZV8MC033840
SJAAM2ZV0MC033914	SJAAM2ZV4MC033849	SJAAM2ZV8MC033854
SJAAM2ZV0MC033945	SJAAM2ZV4MC033852	SJAAM2ZV8MC033885
SJAAM2ZV0MC033959	SJAAM2ZV4MC033883	SJAAM2ZV8MC033899
SJAAM2ZV0MC034027	SJAAM2ZV4MC033897	SJAAM2ZV8MC033904
SJAAM2ZV0MC034044	SJAAM2ZV4MC033902	SJAAM2ZV8MC033918
SJAAM2ZV0MC034061	SJAAM2ZV4MC033916	SJAAM2ZV8MC033935
SJAAM2ZV1MC033775	SJAAM2ZV4MC033933	SJAAM2ZV8MC033949
SJAAM2ZV1MC033789	SJAAM2ZV4MC033995	SJAAM2ZV8MC033952
SJAAM2ZV1MC033792	SJAAM2ZV4MC034001	SJAAM2ZV8MC033966
SJAAM2ZV1MC033811	SJAAM2ZV4MC034015	SJAAM2ZV8MC033997
SJAAM2ZV1MC033825	SJAAM2ZV4MC034032	SJAAM2ZV8MC034003
SJAAM2ZV1MC033839	SJAAM2ZV4MC034077	SJAAM2ZV8MC034017
SJAAM2ZV1MC033842	SJAAM2ZV5MC033777	SJAAM2ZV8MC034034
SJAAM2ZV1MC033856	SJAAM2ZV5MC033780	SJAAM2ZV8MC034048
SJAAM2ZV1MC033873	SJAAM2ZV5MC033794	SJAAM2ZV8MC034051
SJAAM2ZV1MC033890	SJAAM2ZV5MC033813	SJAAM2ZV8MC034082
SJAAM2ZV1MC033906	SJAAM2ZV5MC033827	SJAAM2ZV8MC034292
SJAAM2ZV1MC033923	SJAAM2ZV5MC033830	SJAAM2ZV9MC033779
SJAAM2ZV1MC033940	SJAAM2ZV5MC033861	SJAAM2ZV9MC033796
SJAAM2ZV1MC033954	SJAAM2ZV5MC033875	SJAAM2ZV9MC033815
SJAAM2ZV1MC033999	SJAAM2ZV5MC033892	SJAAM2ZV9MC033829
SJAAM2ZV1MC034005	SJAAM2ZV5MC033908	SJAAM2ZV9MC033832
SJAAM2ZV1MC034019	SJAAM2ZV5MC033911	SJAAM2ZV9MC033846
SJAAM2ZV1MC034022	SJAAM2ZV5MC033939	SJAAM2ZV9MC033863
SJAAM2ZV1MC034294	SJAAM2ZV5MC033942	SJAAM2ZV9MC033877
SJAAM2ZV2MC033767	SJAAM2ZV5MC033956	SJAAM2ZV9MC033880
SJAAM2ZV2MC033770	SJAAM2ZV5MC034007	SJAAM2ZV9MC033894
SJAAM2ZV2MC033834	SJAAM2ZV5MC034038	SJAAM2ZV9MC033913



BENTLEY

Bentley
Bulletin

Aftersales

21-030

May 7, 2021

To: Sales, Marketing, Parts, and Service

Subject: Stop Sale/Stop Delivery: Bentayga: Rear Training Arm Nut Recall

SJAAM2ZV2MC033848	SJAAM2ZV6MC033772	SJAAM2ZV9MC033930
SJAAM2ZV2MC033851	SJAAM2ZV6MC033819	SJAAM2ZV9MC033944
SJAAM2ZV2MC033879	SJAAM2ZV6MC033836	SJAAM2ZV9MC033961
SJAAM2ZV2MC033882	SJAAM2ZV6MC033853	SJAAM2ZV9MC033989
SJAAM2ZV2MC033896	SJAAM2ZV6MC033884	SJAAM2ZV9MC033992
SJAAM2ZV2MC033901	SJAAM2ZV6MC033898	SJAAM2ZV9MC034009
SJAAM2ZV2MC033915	SJAAM2ZV6MC033903	SJAAM2ZV9MC034012
SJAAM2ZV2MC033929	SJAAM2ZV6MC033917	SJAAM2ZV9MC034026
SJAAM2ZV2MC033932	SJAAM2ZV6MC033920	SJAAM2ZV9MC034057
SJAAM2ZV2MC034000	SJAAM2ZV6MC033934	SJAAM2ZV9MC034267
SJAAM2ZV2MC034031	SJAAM2ZV6MC033948	SJAAM2ZVXMC033791
SJAAM2ZV2MC034045	SJAAM2ZV6MC033951	SJAAM2ZVXMC033810
SJAAM2ZV2MC034076	SJAAM2ZV6MC034002	SJAAM2ZVXMC033824
SJAAM2ZV3MC033776	SJAAM2ZV6MC034033	SJAAM2ZVXMC033838
SJAAM2ZV3MC033793	SJAAM2ZV6MC034047	SJAAM2ZVXMC033841
SJAAM2ZV3MC033809	SJAAM2ZV7MC033778	SJAAM2ZVXMC033855
SJAAM2ZV3MC033812	SJAAM2ZV7MC033781	SJAAM2ZVXMC033872
SJAAM2ZV3MC033843	SJAAM2ZV7MC033795	SJAAM2ZVXMC033886
SJAAM2ZV3MC033857	SJAAM2ZV7MC033800	SJAAM2ZVXMC033905
SJAAM2ZV3MC033860	SJAAM2ZV7MC033814	SJAAM2ZVXMC033922
SJAAM2ZV3MC033874	SJAAM2ZV7MC033828	SJAAM2ZVXMC033953
SJAAM2ZV3MC033888	SJAAM2ZV7MC033831	SJAAM2ZVXMC034021
SJAAM2ZV3MC033891	SJAAM2ZV7MC033859	SJAAM2ZVXMC034049
SJAAM2ZV3MC033907	SJAAM2ZV7MC033876	SJAAM2ZVXMC034245
SJAAM2ZV3MC033910	SJAAM2ZV7MC033893	SJAAM4ZV0MC033858
SJAAM2ZV3MC033938	SJAAM2ZV7MC033909	SJAAM4ZV4MC034043
SJAAM2ZV3MC033941	SJAAM2ZV7MC033943	SJAAM4ZV4MC034060
SJAAM2ZV3MC033969	SJAAM2ZV7MC033957	SJAAM4ZV5MC033807
SJAAM2ZV3MC033972	SJAAM2ZV7MC033960	SJAAM4ZV9MC033924
SJAAM2ZV3MC034023	SJAAM2ZV7MC033974	SJAAM4ZVXMC033950
SJAAM2ZV3MC034037		

Sincerely,
Bentley Aftersales