

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6183
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 10, 2022

Subject: REVISION: N20232425-03 - Safety Recall
Roof Rail Air Bag Inflator May Rupture
Revised QR Code Recording Process

Models: 2015-2016 Chevrolet Silverado 1500
2015-2016 Chevrolet Silverado 2500/3500
2015-2016 GMC Sierra 1500
2015-2016 GMC Sierra 2500/3500

To: All General Motors Dealers

The Serial Recording information regarding the QR code process has been updated in this bulletin. Please discard all previous copies of N202324251.

Question and Answer Document (Q&A)

Attached to this message you will find a document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

Working Capital Assistance Program (WCAP) Eligibility

Vehicles which were in dealer inventory at the time of this bulletin release were eligible for WCA. Please refer to the attached bulletin and GlobalConnect Message GCUS-9-9188 for additional information.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS