



419 W. Pike St., Jackson Center, OH 45334

## **IMPORTANT SAFETY RECALL**

Airstream Motor Homes

**NHTSA 21V-590**

**Date:** 9/3/21

**TO:** Airstream Dealer

### **PROBLEM:**

In certain 2022 Interstate 24X motorhomes with the 2000w inverter, may have an inverter that has been wired with incorrectly sized wires and circuit breakers which may cause the inverter electrical circuit to become overloaded. To correct this, additional wiring and circuit breakers will be installed.

### **RANGE OF VEHICLES INVOLVED:**

2022 Airstream Interstate 24X built between: **April 12, 2021 and July 16, 2021.**

Serial number range: **308088 - 308735**

**Note:** Because our VINs do not run in a contiguous series, there will be units in the VIN range which will not be affected by this recall.

### **Flat Rates:**

The time allowed for this repair is **2.5 hour** per motorhome to correct the wiring. Please use operation code **TCSBR8394100** when submitting a claim for warranty reimbursement.

### **WARRANTY REIMBURSEMENT:**

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is **2.5 hrs.**

### **SERVICE ACTION:**

Additional wiring and circuit breakers will be installed.



Please contact the **Airstream Warranty Department at 877-596-6111 Ext. 7401** with any questions, or concerns regarding this recall.

**Notice:**

**Per CFR § 577.13(b) - Notification to dealers and distributors.** It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or noncompliance is remedied.

encl. – Owners Letter, Repair Procedure



**Rick March**

General Manager of Airstream Customer Service Group

Re: NHTSA Recall No. 21V-590