VOLKSWAGEN DEALER COMMUNICATION

Advance Notice - Safety Recall 51H5 / Roof Reinforcement

This notice is for:	 ✓ Dealer F ✓ General ✓ Sales Matrix 	Manager	 ✓ Service Ma ✓ Parts Mana ✓ Service Co 	ager ✓ Technic	ty Administrator cians
Date:	September 28, 2021				
Issue:	Vehicles included in this recall may have been repaired after having sustained roof damage with an unapproved roof reinforcement replacement part.				
	If the vehicle was repaired with an incorrect roof reinforcement replacement part, there is the risk that, in the event of a severe crash, the roof frame deformation could be higher and the functionality of the restraint systems, such as head curtain airbags, can be influenced. This may lead to the increased risk of injury to vehicle occupants in the event of a severe crash.				
Repair:	REPAIR NOT YET AVAILABLECheck daily campaign open inventory report or OMD for affected vehicles in				
	inventory.				
		Beginning	Ending		Vehicle
Affected Vehicles	Country	Model Year	Model Year	Vehicle	Count
Affected Vehicles	Country USA			Vehicle TIGUAN LWB	
Affected Vehicles		Model Year	Model Year		Count
Affected Vehicles	USA CAN *Counts reflect screen in Elsa	Model Year 2018 2018 ct overall population	Model Year 2018 2018 n; some vehicles ma to verify that a VIN Q	TIGUAN LWB	Count 2 1 Check Campaigns/Actions
Affected Vehicles Notes:	USA CAN *Counts refle screen in Elsa campaign inqu	Model Year 2018 2018 ct overall population on the day of repair iry & verification so	Model Year 2018 2018 n; some vehicles ma to verify that a VIN cource.	TIGUAN LWB TIGUAN LWB v have already been repaired. C	Count 2 1 Check Campaigns/Actions ion. Elsa is the <u>only</u> valid

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Volkswagen Public Relations.