

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6157
URGENT - DISTRIBUTE IMMEDIATELY

Date: May 10, 2022

Subject: N212349040-01 - Safety Recall - Recall Reinstated
Driver Front Airbag Inflator May Rupture

Models: 2008-2017 Buick Enclave
2013-2017 Chevrolet Traverse

To: All General Motors Dealers

On April 28, 2022, General Motors temporarily suspended Safety Recall N212349040 via GM GlobalConnect Message GCUS-3-2513. The purpose of this message is to inform dealers that dealers may now resume repairs under this Safety Recall.

Involved vehicle status in IVH will be changed back to an "Open" status on May 10, 2022. We apologize for any inconvenience this situation may have caused.

Question and Answer Document (Q&A)

Attached to this message you will find an updated document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS