



**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: 21V-015
Safety Advisory: 21-394
February 8, 2021

IMPORTANT SAFETY RECALL

«Owner_name»
«Street»
«Street_2»
«City», «State» «Zip»

This notice applies to your vehicle: «VIN»

Dear «Owner_name»:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model 2021 Redwood Fifth Wheels. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for
this recall***

It has been decided that the vehicles in the recall population have a Dexter axle using a substitute spring with U-bolts that were not properly torqued. Under certain conditions during travel, if the improperly torqued U-bolts come loose, there is an increased risk of the axle sliding back on the spring, which could result in poor vehicle handling and/or vehicle crash.

***What we
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to torque the axle spring U-bolts to 110 ft lbs. The service and parts required for this corrective action will be provided at no charge to you.

***What we
need you to
do***

Springs can be visually inspected to see if they are misaligned or if the U-bolts are loose. The U-bolt fasteners can be properly torqued to 110 ft lbs. As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1 hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.) Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your attention and cooperation in this matter.

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Vice President Service Operations
cc: National Highway Traffic Safety Administration (NHTSA)



**PO Box 2000 – Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com**