

IMPORTANT SAFETY RECALL NOTICE 2021060008

This notice applies to your vehicle

VIN:

Check Torque on Front Door Hinge Screws
NHTSA Recall ID: 21V359

June, 2021



A remedy is available for your vehicle.

Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.

This repair will be provided free of charge.

Dear Valued Freightliner Sprinter Owner:

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG ("MBAG"), the manufacturer of Freightliner Sprinter Vans has decided that a defect which relates to motor vehicle safety exists in certain Model Year (MY) 2020 Freightliner Sprinter vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.



What is the issue?

On certain MY20 Sprinter vehicles, the screws for the front door hinges may not have been tightened according to specification. If the door hinge screws are not tightened with the specified amount of torque, it's possible that the pretensioning force of the screw could decrease and eventually cause a change in the opening/closing behavior of the door, as well as changes in door gap dimensions. This could increase the risk of injury in the event of a crash.



What will your Freightliner Dealer do?

An authorized Freightliner dealer will check the screws on the front door hinges and re-torque to specification if necessary.



Steps to take.

For additional information and to schedule an appointment, please contact your preferred authorized Freightliner Sprinter dealer at your earliest convenience. To locate your nearest Freightliner Sprinter dealers, please visit https://www.freightlinersprinterusa.com/freightliner/shopping-tools/find-a-dealer or call 1-800-367-6372 Please mention you are scheduling an appointment to check the torque on front door hinge screws under Recall Campaign # 2021060008.

This could take approximately 45 minutes. This service will be provided free of charge. You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

Please visit www.freightlinersprinterusa.com/freightliner/owners-resources/recall. Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Freightliner Sprinter dealer. A VIN-based recall lookup tool on our website now offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed.

Sincerely, Daimler Vans USA

Daimler Vans USA, LLC

A Daimler AG Company One Mercedes-Benz Drive Sandy Springs, GA 30328 Phone: (770) 705-0600



IMPORTANT SAFETY RECALL

Additional Information for Owners:

If an authorized Freightliner Sprinter dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to https://www.safercar.gov.

INADODTANIT

									IIVIPORTANT									VIN:										
	LOSED								IS VEH AIL BO																			
	EXPO LEAS SCRA SOLE STOL OTHI	E, VI APPE) .EN	HIC	LE RE	ETUF	RNEI	D																					
	NEW OR MY N							IS:																				
Las	t Nam	e, Fir	st Na	me																								
Street																									Apt	-		
City													ı	ı	1	ı		1	1	1		State	9	Z	ZIP			
Em	ail Ad	dress		l.									1	1	1		<u> </u>	<u> </u>	1		<u> </u>		ı					
															1									Ī	Ī			
Phone (numbers only)																		only)				<u>.</u>	<u>.</u>					
Date						Sig	nat	ture																				

