



**IMPORTANT SAFETY RECALL 2021070035**  
This notice applies to your vehicle, VIN: [REDACTED]  
**Replace Overflow Pipe and Transmission Fluid Filter**  
NHTSA Recall #21V539

September, 2021

2021070035  
[REDACTED]  
[REDACTED]  
[REDACTED]

- A remedy is available for your vehicle.
- Schedule an appointment with your authorized Mercedes-Benz dealer as soon as possible.
- This repair will be provided free of charge.



Dear Mercedes-Benz Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mercedes-Benz AG (“MBAG”), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year (“MY”) 2013 GLK-Class vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

**What is the CONCERN?**

In certain MY 2013 Mercedes-Benz GLK250 BluTec vehicles, an incorrect type of overflow pipe and transmission fluid filter might have been installed by an authorized Mercedes-Benz dealer while performing a prior repair. Installation of an incorrect overflow pipe could lead to overfilling the transmission with transmission fluid. Depending on the driving situation, this might result in an overflow of transmission fluid through the transmission vent, which can increase the risk of a fire. Depending on the quantity of leaked fluid, the risk of a crash for other road users could increase. In addition, due to the reduced filtration performance of the installed transmission oil filter, a failure of the transmission control unit might occur, which could cause a vehicle stall and increase the risk of a crash.

**What will your DEALER DO?**

An authorized Mercedes-Benz dealer will replace the overflow pipe and transmission fluid filter on the affected vehicles. **This service will be provided free of charge.** We are dedicated to always delivering the best customer experience, and respect for your time is a top priority. While the minimum repair time can be less than 3 hours, your dealer can provide you with a better estimate of the overall time for this service visit. As a matter of normal service process, an authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time.

**What should YOU DO?**



To find the most convenient authorized Mercedes-Benz dealer from your smartphone, scan the QR code to the left.

For additional information and to schedule an appointment, please contact your preferred authorized Mercedes-Benz dealer at your earliest convenience. To locate authorized dealers see [www.MBUSA.com/recall](http://www.MBUSA.com/recall). **Please mention you are scheduling an appointment to replace the overflow pipe and transmission fluid filter on the affected vehicles under Recall Campaign # 2021070035.** You may be asked for your 17-digit Vehicle Identification Number (VIN) which for your convenience is located above your name at the top of this letter.

**Impacts from COVID-19:** Your health and safety remain our top priority. The Mercedes-Benz dealerships remaining open for recall repairs and service are closely following the guidelines set forth by the CDC. Pick-up and delivery may be available. Your preferred authorized Mercedes-Benz dealer can confirm availability.

In the event that you are no longer the vehicle owner, or have had a change of address, please complete the reverse side and return the updated information in the enclosed envelope.

**Information for Owners**

If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 business days to comply with Federal Regulations.

If you have already paid to have this recall condition corrected you may be eligible to receive reimbursement. Requests for reimbursement may include parts, labor, fees and taxes. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Mercedes-Benz dealer. Please see the following page for more information.

A VIN-based recall lookup tool on our MBUSA.com website offers a search feature that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See [www.mbusa.com/recall](http://www.mbusa.com/recall). Should you have any questions or encounter any difficulty regarding this Recall Campaign, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372).

If an authorized Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to <https://www.safercar.gov>.

We apologize for any inconvenience this situation may cause you.

Sincerely,

Mercedes-Benz USA

Mercedes-Benz USA, LLC  
A Daimler AG Company  
One Mercedes-Benz Drive  
Sandy Springs, GA 30328  
Phone (770) 705-0600

