



RV CHASSIS
A Shyft Group Brand

1000 Reynolds Road, Charlotte, MI 48813 | P:517.543.6400
SPARTANRVCHASSIS.COM

November 16, 2021



IMPORTANT SAFETY RECALL – 21V-776

This notice applies to the vehicle identification number in the label below.

4VZDR1A90MC 

Dear Valued Customer,

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

The Shyft Group, Inc. has decided that a defect which relates to motor vehicle safety exists in certain 2020, 2021 and 2022 model year K1 and K2 model Spartan RV Chassis.

What is the Defect?

Certain rear suspension mounting fasteners that attach the rear drive axle to the rear suspension may not have been tightened to their proper value. As a result, the fasteners could break or be loose enough to allow the rear drive axle to shift.

What is the Safety Risk?

A shift in the rear drive axle could increase the risk of a crash.

What is the Warning?

The rear drive axle could shift without warning.

What is the Remedy?

The rear suspension fasteners checked for damage and if damaged they will be replaced and tightened to the correct torque value. If there is no damage and no torque mark, the fasteners will be tightened to the correct torque value. The inspection of the fasteners should take no more than 0.5 hour. To replace and tighten the fasteners to the correct torque value should take no

more than 2 hours. However, due to scheduling times the service provider may need your vehicle for longer.

What You Should Do:

Call Spartan RV Chassis at 1-800-543-4277 to locate a qualified service center near you. Steps will be taken to ensure the work is performed at the nearest service center.

Leased Vehicles:

The lessor must notify the lessee by first class mail within ten (10) days from receipt of their owner notification letter from the manufacturer; both for the initial notification and all subsequent notifications.

Reimbursement:

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Spartan RV Chassis at 1-800-543-4277.

Reply Card:

Please fill out the enclosed prepaid postcard and mail it to us if you have changed your address, sold, or traded the vehicle.

If the authorized service center has failed or is unable to remedy the defect without charge and within a reasonable time, contact Spartan RV Chassis at 1-800-543-4277. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, D.C. 20590 or call the Auto Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov> if you feel the manufacturer has failed or is unable to remedy the defect without charge.

We regret any inconvenience this service may cause you. Your safety and continued satisfaction with the quality and performance of your chassis is of the utmost concern to us.

Sincerely,

Spartan RV Chassis