

### SIB 65 09 21

2023-05-17

RECALL 21V-401: DRIVER'S FRONT AIR BAG (NADI) INFLATOR

This Service Information Bulletin (Revision 4) replaces SI B65 09 21 dated December 2022.

☐ THIS REPAIR IS MOBILE FRIENDLY

What's New (Specific text highlighted):

- Procedure Single vs dual stage ignitors clarified
- Part number supersession

### **MODEL**

E-Series	Model Description	Production Date
E46	3 Series Sedan	June 5, 1998 – June 27, 2000

## **AFFECTED VEHICLES**

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

### **SITUATION**

BMW AG is conducting a Voluntary Safety Recall (effective May 28, 2021) on certain Model Year 1999 – 2001 BMW 3 Series vehicles that were produced between June 5, 1998 and June 27, 2000.

These vehicles were recalled in 2019 but were only inspected, and will now need a replacement air bag inflator.

The single-stage Takata Non-Azide (NADI) Driver gas generator, also known as an air bag inflator, may have been produced with an insufficient seal that could allow moisture to enter the gas generator. The gas generator is a separately replaceable part of the air bag module.

### OTHER AIR BAG-RELATED FAULTS AND REPAIRS

This Recall applies to an operational driver's front air bag. The issue addressed will not cause an air bag (SRS) malfunction light to illuminate. It will also not prevent the system from deploying in a front-end collision.

However, a recalled vehicle can arrive at your center with an air bag malfunction light illuminated.

It is important to notify the customer that diagnosing other air bag-related system issues may be required and this diagnosis and corresponding repair work, if needed, is not covered by this Recall.

In this case, replacing the driver's front air bag gas generator will not correct the other fault code(s).

## **CAUSE**

The single-stage Takata Non-Azide (NADI) Driver gas generator, also known as an air bag inflator, may have been produced with an insufficient seal that could allow moisture to enter the gas generator. The gas generator is a separately replaceable part of the air bag module.


### **CORRECTION**

The current installed air bag gas generator must be replaced

In the following cases, the gas generator replacement should not be performed. Instead, the complete air bag assembly must be replaced:


- Threaded bolts are damaged
- Threaded bolts are bent or corroded
- The generator cannot be removed from the air bag without excess force
- If the target tightening torque of the nuts cannot be achieved (5 Nm in a star pattern sequence)
- If there is a gap between the generator & air bag that is not closed up when tightening the nuts
- If there is damage to the air bag cover that may impede deployment of the air bag

## **PROCEDURE**




Follow all safety precautions when handling air bags.

Remove Basic Drivers air bag as per REP 32 34 010 "Removing and installing/replacing air bag unit"



Remove **Sports Drivers air bag** as per **REP 32 34 020** "Removing and installing/replacing the air bag unit (sports steering wheel, inserted air bag unit)"

Copyright ©2023 BMW of North America, Inc.



Once the air bag is removed and the wiring is disconnected, turn the air bag over to read the parts label(s) on the gas generator on the back.

**Basic Driver's air bag,** showing the location of the parts label.



**Sport Driver's air bag,** showing the location of the parts label.

### Gas generator serial number decoding:

Digits 1-2 = Type of gas generator

Digit 3 = Production Line Digit 4 = Production year

Digit 5-11 = Serial #

\*NOTE: The serial number can have 10 or 11 characters. Only the first 10 characters counted from the left are relevant for the check. The 11th digit can be disregarded for the repair covered by this SIB

All original gas generator serial numbers which begin with BK MUST be replaced- refer to the table below. These are SINGLE ignition stage gas generators with a white label.

Digits 1-	Digit 4	Digit 5-10	Repair Category
ВКС	H, J	ALL	Drivers air bag gas generator must be replaced
BK1	H, J, K, L, M, N, P, Q, R, U, V	ALL	Drivers air bag gas generator must be replaced
BK5	-	ALL	Drivers air bag gas generator must be replaced

Copyright ©2023 BMW of North America, Inc.

about:blank 3/10



**Situation 1:** If the serial number is not legible and cannot be identified, or the driver air bag gas-generator is NOT a type BK; submit a Reply Requested TSARA case for support.

- Title the TSARA case NADI TAKATA RECALL 21V-401
- The case should include pictures of the gas generator and its serial number

You will be instructed by TSARA on how to proceed.



**Situation 2**: Some vehicles may have air bag control unit MRS III which was introduced in some models starting September 1999 and supports a dual stage gas generator.

**Standard steering wheel** gas generator pictured.

Takata air bags with different chemical compositions (DUAL STAGE IGNITOR with white label) are not affected by this recall and DO NOT need to be replaced.

Reinstall the driver's air bag.

Submit an INFO ONLY TSARA case with a picture of the gas generator serial number to document this repair.

Claim Defect Code **0032200300** and labor op (main/plus work as applicable), **invoice no parts**.

In this situation, labor with no parts invoiced applies. The warranty claim will be forced into manual review to confirm that a part replacement was not required.



Please make sure to reference the TSARA Info Case number in the Warranty claim comments section to support this inspection-only procedure.

**Situation 3:** Some vehicles may have air bag control unit MRS III which was introduced in some models starting September 1999 and supports a dual stage gas generator.

This later production date **Sport steering wheel** gas generator (pictured) was retrofitted into the vehicle and is not covered under warranty replacement.

These gas generators must be replaced

Submit an INFO ONLY TSARA case with a picture of the gas generator serial number to document this repair.

- Claim Defect Code 0032200300 and only the labor op (main/plus work as applicable), invoice no parts here, see below.
- Then claim Defect Code 32349003TK for the applicable parts only. See SI <u>B65</u> <u>02 17</u> only for replacement parts information.

The claim [H1] [CSC2] will be forced into manual review to confirm that the correct part replacement was performed.

Please make sure to reference the TSARA Info case number in the Warranty claim comments section to support this replacement.

The serial number of the checked gas-generator AND the new gas-generator must both be stated on the repair order and in the comments section of the warranty claim.

Copyright ©2023 BMW of North America, Inc.

about:blank 5/10

Refer to SI B65 03 20 for details on how to replace a gas generator.

## PARTS INFORMATION

Please refer to the Parts Matrix for the ordering procedure.

Only use and invoice the part numbers below that apply.

Performing a part number look-up in ETK (EPC) by VIN or model in place of using/invoicing the following part numbers may result with the wrong part numbers being invoiced and installed. This could delay the payment of claim.

Part Number	Description	Quantity
32 30 5 A1B D99		
Or:	Gas Generator repair kit	1
32 30 5 A1D 756	·	

If a complete air bag is needed as per the CORRECTION section above:

- Please order the parts for a specific VIN only and not for stock.
- In the Warranty Comments section of your claim you must let us know what is preventing you from replacing the gas generator.
- Parts returned under this recall are subject to inspection to confirm the correct repair was performed.

\_

Part Number	Description	Quantity
32 34 5 A1B DB4	Standard air bag unit <b>WITHOUT</b> multifunction switches	1 (if required)
32 34 5 A1B DB5	Standard air bag unit WITH multifunction switches	1 (if required)
32 34 5 A1B DB3	Air bag unit, sports steering wheel	1 (if required)

Or:

For Defect Code 32349003TK Air Bag Replacement Part Information (With WP # 9 or 10)

**See SI** <u>B65 02 17</u> only for the applicable replacement part information to claim with the above Defect Code-related repair.

## PARTS RETENTION AND RETURN

Refer to SI B01 26 22

## **CLAIM INFORMATION**

Reimbursement for this Recall will be via normal claim entry utilizing the applicable work package information below, and when applicable, the part number listed above that applies.

Plus work	Vehicle is already in the workshop for another repair
Main	The vehicle arrives at your center and this Recall Campaign shows open (No
work	other Main work will be performed/algimed during this workshop visit) Convright ©2023 RMW of North America Inc

about:blank 6/10

Defect	0032200300	E46 Reworking driver's airbag (NADI - part IV)
Code:		

## Inspect the air bag and the gas generator is replaced (Recall is CLOSED)-

Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance
# 1	00 70 951	Checking the driver's air bag and replacing the gas generator (Plus work)	7 FRU
Or:			
# 2	00 70 397	Checking the driver's air bag and replacing the gas generator (Main work)	8 FRU

Or:

## As applicable below, the air bag module complete is replaced (Recall is CLOSED)-

Work Pkg	Labor Operation	Description	Labor Allowance
#3	00 70 952	Replace the driver's air bag (module complete, replacement part is available) after abandoning the replacement of the gas generator (Plus work)	4 FRU
Or:			
# 4	00 70 398	Replace the driver's air bag (module complete, replacement part is available) after abandoning the replacement of the gas generator (Main work)	5 FRU
Or:			
# 5	00 70 953	Replacing the driver's air bag module (complete, replacement part is available) (Follow-up work after abandoning the replacement of the gas generator was claimed prior with DC 32 34 90 03 00) (Plus work)	3 FRU
Or:			
# 6	00 70 399	Replacing the driver's air bag module (complete, replacement part is available) (Follow-up work after abandoning the replacement of the gas generator was claimed prior with DC 32 34 90 03 00) (Main work)	5 FRU

Or:

# White Label Gas Generator – With TSARA Case, Inspection only, NO part replacement is necessary (Recall is CLOSED)-

Defect Code:	0032200300	E46 Reworking driver's airbag (NADI - part IV)			
:	:				
Work Pkg	Labor Operation	Description	Labor Allowance		
#7	00 70 953	White Label Gas Generator driver's air bag module: Checking the driver's air bag only with a TSARA case, no replacement is necessary (Plus work)	3 FRU		
Or:					
#8	00 70 399	White Label Gas Generator driver's air bag module: Checking the driver's air bag only with a TSARA case, no replacement is necessary (Main work)	5 FRU		

Or:

# A. Yellow Label Gas Generator (Line Item One, Labor Only) – With TSARA Case replace the driver's air bag module complete (Recall is CLOSED)-

Defect Code:	0032200300	E46 Reworking driver's airbag (NADI - part IV)	
:			
Work Pkg	Labor Operation	Description	Labor Allowance
# 9	00 70 953	Yellow Label Gas Generator driver's air bag module: Checking the driver's air bag and replace the driver air bag module complete with a TSARA case (Plus work)	3 FRU
Or:			
# 10	00 70 399	Yellow Label Gas Generator driver's air bag module: Checking the driver's air bag and replace the driver air bag module complete with a TSARA case (Main work)	5 FRU

And, with the above claim submission (A) for the labor portion:

# B. Yellow Label Gas Generator (Line Item Two, Parts Only) – With TSARA Case replace the driver's air bag module complete (Recall is finalized)-

(Parts Only)	Defect Code:	32349003TK	E46 Driver's Air Bag NADI Yellow Label Gas Generator (Parts Only)
--------------	--------------	------------	---

See SI B65 02 17 for the parts information only and claim applicable replacement parts as a separate line item under **DC 32 34 90 03 TK**.

Copyright ©2023 BMW of North America, Inc.

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

### **Claim Repair Comments**

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B65 09 21 WP 1), unless otherwise required by State law.

Additionally, for Work Packages # 7, 8, 9, or 10; also reference the corresponding TSARA case.

### Reimbursement of Prior Customer-Pay Repairs (TREAD Act)

With this Technical Campaign, a prior repair reimbursement is not likely. Typically, a customer would have their driver's front air bag module replaced as a result of an accident. In such a case, either an insurance company or the customer themselves paid for the replacement of the above-mentioned air bag module in conjunction with the accident repairs. Such cases are not covered by this campaign and are not entitled to reimbursement.

### FEEDBACK REGARDING THIS BULLETIN

Technical Feedback	To submit feedback for the technical topics of this bulletin: Submit your feedback in the rating box at the top of this bulletin
Warranty Feedback	To submit feedback for the CLAIMS section of this bulletin: Submit an IDS ticket to the Warranty Department, or use the chat available in the Warranty Documentation Portal
Parts Feedback	To submit feedback for the PARTS section of this bulletin: Submit an IDS ticket to the Parts Department

### Supporting Materials

picture as pdf B650921 21V-401 E46 DAB QA 03 Jun2021.pdf

picture as pdf B65 09 21 REP 32 34 010 R I airbag unit.pdf

picture as pdf B650921 Recall Notice.pdf

picture as pdf B65 09 21 REP 32 34 020 R I airbag sport.pdf

picture as pdf B65 09 21 Gas Generator REP.pdf

Attachment to B65 09 21 June 2021

## **SAFETY RECALL NOTICE**

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Recall 21V-401: Driver's Front Air Bag (NADI) Inflator - B65 09 21

BMW AG is conducting a Voluntary Safety Recall (effective May 28, 2021) on certain Model Year 1999 – 2001 BMW 3 Series vehicles that were produced between June 5, 1998 and June 27, 2000.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.

BMW Group - AIR: 2019-12-03 / 11:13

Retailer: -/-Model: 328I A

Development code: E46 Model code: AM63 Lead type: AM63

### Repair instruction

## Removing and installing/replacing the airbag unit (sports steering wheel, inserted airbag unit)

32 34 020 | REP-REP-RAE4632-3234020SMART - V.2

### 32 34 020 Removing and installing/replacing the airbag unit (sports steering wheel, inserted airbag unit)



### Warning!

Observe the following instructions to avoid any risk of injury by the airbag unit.

- Comply with safety regulations for handling components with gas generators.
- Do not exert any force on the airbag unit.
- Use only specified release tool for the airbag unit.

<u>Note:</u> Incorrect handling may result in triggering of the airbag unit and thereby cause serious injury.



### Attention!


Steering wheel must be replaced if airbag unit has been triggered!

Follow procedure after airbag deployment.



### Necessary preliminary work:

· Disconnect battery earth lead



### Installation note:

When installing a new airbag unit (see table below), the available ground spring (1) must be removed from the base plate of the steering wheel.

Pull off spring (1) from screw.


Omitting the ground spring (1) on new airbag units is not a safety hazard.


Introduction dates of new airbag units:

E46: 01/2002

E53: 02/2003

E39: 03/2002





Insert a screwdriver through the opening on the rear side of the steering wheel and press on the lock. In the event of a spring resistance, press the lock up to the limit position and simultaneously pull away the airbag unit (1) from the steering wheel.


Repeat the process on the opposite side.

The process on the next image is illustrated without the airbag unit to make it clearer.



R32 0191

Use the screwdriver (2) to press on the lock (1).



### Installation note:

Make sure electrical leads are correctly positioned.


Insert the airbag unit into the locks with the hooks and press it into the steering wheel.



### Warning!

Danger of injury!

Airbag unit may only be set down with the airbag itself facing upwards.



### Unlocking the airbag plug connection:


Lever out the lock (1) with a screwdriver.

Open the locks (1) and pull off the connector.

Remove airbag unit.

### Installation note:

Connect plugs to connections of same colour on airbag unit.



Attachment B65 09 21 June 2021

Replacing the gas generator for the driver's airbag »

## WARNING

Pyrotechnic components.

Danger! Immobilization period-threatening injuries!

- All work on pyrotechnic parts may be carried out by technically experienced and appropriately trained personnel only.
- Replace any damaged part or ones that have been dropped.
- For additional information see: 72 00 Safety regulations on handling components with gas generators.

## RISK OF DAMAGE



Electrostatic discharge.

Damage to or destruction of electrical components.

- Leave electrical components in original packaging until just before they are installed. Use the original packaging only for any return shipments. Always package removed components straight away.
- Read and comply with user information on using the associated special tool 12 7 060.
- Only tap the housings of electrical components. Do not tap pins or multi-pin connectors directly.
- Wear electrically conductive clothing and antistatic shoes (with ESD symbol).
- For additional information see: 61 35 ... Notes on ESD (electrostatic discharge) protection
  - 61 35 ... Notes on ESD protection (Electro Static Discharge)

## i TECHNICAL INFORMATION

The work surface must be clean, even, skid-proof and tilt-proof.

## □ NOTE

Only one vehicle may be processed at a time.

Execute repair without interruption.

Interruptions of any kind are not permitted (such as by telephone calls).

The person performing the procedure must not be distracted.

## □ NOTE

The person performing the repair must have a second person available for the entire duration of the repair.

The second person has the following tasks:

Fill in the checklist.


Attach the component(s).

Inspection of work performed.

## Preliminary work

## Preparing the workplace

Workplace for replacement of the gas generator (E46)



- 1 Collection container for disposal of the nuts
- 2 Tools required for the exchange
- 3 Antistatic mat
- 4 New, packaged gas generator
- 5 Scratch-resistant cotton underlay

• Print out the checklist.

## 3234

- Prepare the antistatic mat and cotton pad:
- Have the following tools ready:

Felt pen


Adhesive tape (width min. 25 mm)

Wedge 0 490 539 (00 9 322)

1/4" reversible ratchet
1/4" reversible ratchet



1/4" reversible ratchet with Extension 1/4 inch Extension 1/4 inch



Extension 1/4 inch and Socket wrench for hexagon Socket wrench for hexagon



Socket wrench for hexagon 8 mm

Torque wrench with Socket wrench for hexagon Socket wrench for hexagon



Socket wrench for hexagon 8 mm

## Tightening torques

Gas generator to airbag unit

Nut

Renew nut.


Tightening torque

5Nm

## Main Works


# Replacing the gas generator of airbag unit (standard steering wheel) Prerequisite


Airbag unit is removed.




- Place the airbag unit (1) turned around as shown.
- Note the serial number (2) of the airbag unit (1) on the work order.

• Glue the connector (1) from the previous gas generator of the airbag unit (2) with the adhesive tape so that the contacts cannot be touched.






- Mark a cross (1) with the felt pen to avoid a mix-up with the new gas generator.
- Mark all the four nuts (2) with the felt pen to avoid a mix-up with the new nuts.



• Release both the connectors (1) on the airbag unit (2).

- Auxiliary person: Hold the airbag unit (1).
- Unscrew all the nuts (2) in any order and dispose of immediately in the collection container provided (3).
- Do not reuse the nuts (2).




► Preparing the new gas generator

## RISK OF DAMAGE

Damage to the gas generator.

A damaged gas generator due to, for example, a fall, can lead to malfunctions and must be replaced.

- Handle gas generator carefully.
- Do not use the gas generator after a fall, but replace it.




- Unpack the new nuts (1), reinforcement plate (2), new gas generator (3), cable (4) and sticker (5) and place it as shown.
- Make sure that the groove (arrow) of the reinforcement plate (2) is positioned correctly.
- USA only:

Dispose of the hazard sticker (6).

 Clip in the cable (1) as shown in the new gas generator (2).


The cable (1) and the groove (arrow) of the new gas generator (2) point upwards.

The connector is encoded against incorrect assembly.






RB32 01044



 Remove the previous gas generator (1) and subsequently directly place the new gas generator (2).


The cable and the groove of the new gas generator (2) point upwards.




 Insert the previous gas generator (1) in the packaging (2).

- Position the reinforcement plate (1) over the new gas generator (2).
- Make sure that the groove (arrow) of the reinforcement plate (1) is positioned correctly.

The groove (arrow) points downwards to the left.





## • Auxiliary person:

Hold the airbag unit (6).

Check whether the nuts have been tightened correctly by the executing person.

The noise must be audible while retorquing.

### • Executing person:

Lightly screw on the new gas generator (5) with the new nuts in the screwing sequence (1) to (4).

Tighten the nuts in the screwing sequence (1) to (4).

Retorque the nuts in screwing sequence (1) to (4).

## Tightening torques

## Gas generator to airbag unit

Nut

Renew nut.

Tightening torque

5Nm




Visually inspect the gap (3) between the new gas generator (1), reinforcement plate (2) and airbag unit (4) on all four sides (5).

### Auxiliary person:

Visually inspect the gap (3) between the new gas generator (1), reinforcement plate (2) and airbag unit (4) on all four sides (5).


• If the gap (3) is not OK:




### AIR - Technical documents

Release the screw connection and tighten again as described in the previous step. If the gap is still not OK, then cancel the repair. Install the new airbag unit in this case.

• Connect both the connectors (1) with the airbag unit (2).



- Glue on the first sticker on the airbag unit (1) with the new number on the position (2).
- Glue on the second sticker on the work order.



 Install the airbag unit and horn switch and if necessary, check the multifunction button for operability.

## 3234020

• All except USA:

Affix the hazard sticker (1) externally on the packaging (2).

USA:

Do not affix any hazard sticker (3) externally on the packaging (2).

BMW Group - AIR: 2019-12-03 / 11:12

Retailer: -/-Model: 328l A

Development code: E46 Model code: AM63 Lead type: AM63

### Repair instruction

### Removing and installing/replacing airbag unit

32 34 020 | REP-REP-RAE4632-3234020 - V.1

### 32 34 020 Removing and installing/replacing airbag unit



### Warning!

Observe the following instructions to avoid any risk of injury by the airbag unit.

- Comply with safety regulations for handling components with gas generators.
- Do not exert any force on the airbag unit.
- Use only specified tools for releasing the airbag unit.

Note: Incorrect handling may result in triggering of the airbag unit and thereby cause serious injury.



### Important!


Steering wheel must be replaced if airbag unit has been triggered!

Follow procedure after airbag triggering.



### Necessary preliminary tasks:

• Disconnect battery negative lead



Release screws (Torx T30) on both sides.

### Installation:

Make sure electrical leads are correctly positioned.


Tightening torque 32 34 1AZ.



### Warning!

Danger of injury!

Airbag unit may only be set down with the airbag itself facing upwards.



Press down lock (1) and disconnect plug (2).

Remove airbag unit.



### Replacement:

Disconnect plug connections on airbag unit and remove connecting cable.

### Installation:

Connect plugs to connections of same colour on airbag unit.

## Driver's Front Air Bag Inflator (NADI) Model Year 1999-2001 BMW 3 Series Safety Recall 21V-401

Date Issued: 6/3/2021

### Q1. Which models are included in this Safety Recall Campaign?

Certain Model Year 1999 through 2001 3 Series Sedan, Coupe, and Sportswagon vehicles (E46), produced from June 1998 through July 2000, are potentially affected.

### Q2. Which inflator is affected?

This recall campaign involves vehicles equipped with the single-stage Takata Non Azide Driver Inflator (NADI).

### Q3. What is the specific concern?

Certain NADI inflators may have been produced with an insufficient seal which could allow moisture to enter the inflator.

### Q4. What can happen as a result of this issue?

In a crash where the driver air bag deploys, it may not deploy with sufficient restraint capability which could increase the risk of injury. It is also possible that the air bag housing may explode and could cause metal fragments to pass through the air bag cushion material, which may result in injury or death to the driver and/or other vehicle occupants.

### Q5. Can I continue to drive my vehicle?

Yes. However, when you are notified that a remedy is available for your vehicle, please contact an authorized BMW center immediately to schedule an appointment to have this important **free repair** performed. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

# Q6. I recently had the NADI inflator inspected under a recall and it did not need to be replaced. Why am I being notified again?

Although the NADI inflator was recently inspected under a recall, we have now determined that the inflator needs to be replaced.

### Q7. Why are other BMW models not included?

Other vehicles have driver front air bags that were produced with different inflators.

### Q8. What is the fix?

The driver's air bag inflator will be replaced with a newly designed inflator.

### Q9. How will I be notified of this recall?

Owners are being contacted by First Class mail, advising customers of this recall and to schedule an appointment with an authorized BMW center to have this important Safety Recall performed as soon as possible. If you changed your address or sold the vehicle, please let us know by visiting <a href="https://www.bmwusa.com/recall">www.bmwusa.com/recall</a> and click on "manage recall notices and contact information".

### Q10. Do I have to wait for my letter in order to have my vehicle repaired?

No. Please contact an authorized BMW center immediately to have this important Safety Recall performed as soon as possible. For the latest updates to this Safety Recall please visit <a href="https://www.bmwusa.com/recall.">www.bmwusa.com/recall.</a>

### Q11. Is it possible to find out whether the problem exists in my car?

No. There is no way to detect if your BMW might have an air bag inflator potentially at risk of rupturing upon deployment in an accident.

## **Driver's Front Air Bag Inflator (NADI)** Model Year 1999-2001 BMW 3 Series Safety Recall 21V-401

Date Issued: 6/3/2021

#### Q12. How did BMW become aware of this issue?

BMW became aware of this issue through its quality control procedures.

### Q13. I did not receive a letter from BMW regarding my vehicle. How can I find out if my BMW is included in this recall?

You can enter your vehicle identification number (VIN) at www.bmwusa.com/recall and download a sample owner notification letter and Q&A if your VIN is affected.

### Q14. What if I am not the current owner of this vehicle?

If you changed your address or sold the vehicle, please let us know by visiting www.bmwusa.com/recall and click on "manage recall notices and contact information".

### Q15. Am I eligible for reimbursement under the TREAD Act if I previously replaced my driver's front air bag

In this particular recall, reimbursement is likely not applicable, as you would typically have replaced your driver front air bag module as a result of an accident. In that situation, most likely your insurance company paid for the repair. However, in the very unusual (unlikely) scenario that you previously paid to replace the front air bag module "out-ofpocket" upon learning of this possible defect, you may be eligible for reimbursement. Additional information is provided when BMW mails the letter asking you to make an appointment with an authorized BMW center.